Addendum to Master Plan Tree Survey

CRAIG CROTTY
ARBOR CULTURE
P.O. Box 246
Verdugo City, CA 91046
Tel. 818 957-8824
Cell 818 636-4917
craigcrotty@sbcglobal.net

February 13, 2007

ADDENDUM TO MASTER PLAN
TREE SURVEY OF OCTOBER 3, 2005

c/o Mr. Gordon Jenewein
Mr. Robert L. Hotton
The Master's College
21726 Placerita Canyon Road
Santa Clarita, CA 91321

A total of 353 Oak trees, *Quercus species*, were identified in the Tree Survey of October 3, 2005. Oak trees surveyed meet the size qualification of two inches or greater in trunk diameter at 4.5 feet above grade. Since the original Tree Survey, six Oak trees have fallen or died.


A synopsis of the new numbers and changes:

- Two hundred three (203 Oaks) of these trees will not be impacted in any way by the proposal.
- Seventy seven (77 Oaks) trees will be impacted in various degrees by work proposed within the Tree Protection Zone (defined as an imaginary line drawn around the dripline at a distance five feet beyond the dripline to the tree trunk).
- Twenty two (22 Oaks) will have lesser encroachments where work will occur within five feet of the outer dripline. Oak Tree Guidelines describes tree protection zones of five feet (5 ft.) beyond the dripline or fifteen feet (15 ft.) from tree trunks.
- A total of 45 trees would be removed due to the proposed construction.
- No Heritage Oaks would be removed due to the proposal. Heritage Oak trees are trees with a trunk diameter of 34.4 inches and larger, or in the case of a multi-trunk, with at least two trunks of 22.9 inches each or greater,

Also, there are a number of Oak trees near human-use areas with pre-existing conditions, unrelated to the proposed development. These Oaks have defects posing risks to people and property. Various treatments such as crown reduction pruning, support cabling, and even removal of the tree is recommended to reduce some of these risks.

Relocation of Oak trees proposed for removal was not seen as a viable alternative when compared to purchasing new replacement trees of good condition and appropriate sizes. Relocating Oaks growing on steep slopes usually does not have a high success rate. Relocating Oaks with pre-existing health or structural problems is a set-up for future failure. The original survey did not identify any good relocation candidate trees and, since my last site review, I did not see any new potential relocation candidates.

Any Oak trees to be removed due to proposed construction will be mitigated per the direction of City of Santa Clarita representatives from the City Planning Department and/or the City Oak Tree Specialist. A breach of the Oak Tree ordinance during any site work may result in stop work orders, citations, and suspension of building permits.



Craig Crotty, Consulting Arborist

Supplemental Information:

- Revised Impact Summary 02/13/07
- Tree Removal Value Total

SECTION 2

Revised Impact Summary

TOTAL OAK TREES	**353 Trees**
OAK TREES NOT IMPACTED (added Oaks #130 & 131)	**203 Trees**
LESSER ENCROACHMENT within the outer Five Feet Tree Protection Zone	**22 Trees**
ENCROACHMENT (work within Oak Dripline)	**77 Trees**
TOTAL OAK TREE REMOVALS (Per Plan)	**45 Trees**
DEAD OAKS TREE REMOVALS (Approved Per City Arborist) Tree failures after original Survey (Trees #98, 103, 170, 171, 233, 237)	**6 Trees**
APPRAISED VALUE-OAK TREE REMOVALS (Per Plan)	**$ 555,594.**
HERITAGE OAK REMOVALS	**NONE**

Master's College Oak Tree Valuation

Tree Removal Value

No.	Tree Number		Value
1	6	$	6,479.27
2	7	$	2,529.73
3	8	$	2,962.16
4	9	$	9,736.93
5	10	$	6,479.27
6	11	$	21,066.65
7	12	$	14,839.62
8	13	$	12,648.64
9	30	$	1,491.89
10	31	$	21,989.17
11	32	$	26,111.69
12	33	$	10,106.55
13	34	$	3,942.34
14	58	$	1,059.46
15	59	$	2,168.34
16	60	$	8,843.23
17	61	$	21,989.17
18	62	$	26,111.69
19	63	$	7,228.82
20	64	$	30,032.40
21	65	$	3,423.42
22	66	$	1,261.26
23	67	$	19,711.69
24	68	$	5,124.32
25	69	$	2,538.99
26	70	$	8,843.23
27	71	$	11,639.63
28	72	$	2,529.73
29	73	$	3,942.34
30	93	$	8,843.23
31	94	$	59,149.49
32	95	$	1,780.18
33	96	$	19,711.69
34	97	$	5,124.32
35	99	$	8,007.20
36	100	$	12,719.68
37	101	$	59,149.49
38	177	$	14,721.22
39	178	$	8,345.94
40	179	$	18,057.12
41	180	$	16,895.74
42	187	$	6,863.31
43	188	$	3,379.15
44	351	$	8,007.20
45	352	$	8,007.20
		$	**555,593.79**

CRAIG CROTTY
ARBOR CULTURE
P.O. Box 246
Verdugo City, CA 91046
Tel. 818 957-8824
Cell 818 636-4917
craigcrotty@sbcglobal.net

November 7, 2007

c/o Mr. Gordon Jenewein
Mr. Robert L. Hotton
The Master's College
21726 Placerita Canyon Road
Santa Clarita, CA 91321

ADDENDUM TO MASTER PLAN
TREE SURVEY OF OCTOBER 3, 2005

A total of 353 Oak trees, *Quercus species*, were identified in the Tree Survey of October 3, 2005. Oak trees surveyed meet the size qualification of two inches or greater in trunk diameter at 4.5 feet above grade.

A recent design change, to accommodate fire department access widening requirements, resulted in shifting the 'MacArthur Center' building footprint northward and into two Oak trees.

Oak Trees #152 and #153 will now be removed due to these changes (previously listed as 'work within the dripline'. Removal is due to grading. Both of these Oaks appear to be severely drought stressed, with branch-tip dieback, low-live foliage ratios, and deadwood throughout the crown.

The original appraised values of 2005 for these two trees was based on a 70% condition rating. The condition of both trees has since deteriorated significantly. Thus, I am submitting new appraisals for both Oak Trees #152 and #153 based on a 55% condition rating. The appraised value with current condition is (see attached Appraisal Worksheets):

- Coast Live Oak #152-$ 4,500.
- Coast Live Oak #153-$ 4,500.

Relocation of Oak Trees #152 and #153 is not seen as a viable alternative due to relatively poor condition. Installation of new replacement trees of good condition and appropriate sizes is likely to produce a better success rate and ultimately provide healthier trees.

A synopsis of the new numbers and changes:

- Two hundred three (201 Oaks) of these trees will not be impacted in any way by the proposal.
- Seventy seven (75 Oaks) trees will be impacted in various degrees by work proposed within the Tree Protection Zone (defined as an imaginary line drawn around the dripline at a distance five feet beyond the dripline to the tree trunk).
- Twenty two (22 Oaks) will have lesser encroachments where work will occur within five feet of the outer dripline. Oak Tree Guidelines describes tree protection zones of five feet (5 ft.) beyond the dripline or fifteen feet (15 ft.) from tree trunks.
- A total of 47 trees would be removed due to the proposed construction.
- No Heritage Oaks would be removed due to the proposal. Heritage Oak trees are trees with a trunk diameter of 34.4 inches and larger, or in the case of a multi-trunk, with at least two trunks of 22.9 inches each or greater.

Relocating Oaks growing on steep slopes usually does not have a high success rate. Relocating Oaks with pre-existing health or structural problems is a set-up for failure. The original survey did not identify any good relocation candidate trees and, since my last site review, I did not see any new relocation candidates.

Any Oak trees to be removed due to proposed construction will be mitigated per the direction of City of Santa Clarita representatives from the City Planning Department and/or the City Oak Tree Specialist. A breach of the Oak Tree ordinance during any site work may result in stop work orders, citations, and suspension of building permits.

Craig Crotty, Consulting Arborist

Supplemental Information:

- Revised Impact Summary as of November 7, 2007
  with Tree Removal Value Total
- Condition Adjusted Appraisals for Oaks #152 and #153
- Condensed Site Plan

SECTION 2

Revised Impact Summary

TOTAL OAK TREES	**353 Trees**
OAK TREES NOT IMPACTED **(added Oaks #130 & 131)**	**201 Trees**
LESSER ENCROACHMENT **within the outer Five Feet Tree Protection Zone**	**22 Trees**
ENCROACHMENT (work within Oak Dripline)	**75 Trees**
TOTAL OAK TREE REMOVALS (Per Plan) **(added Oaks #152 &153)**	**47 Trees**
DEAD OAKS TREE REMOVALS (Approved Per City Arborist) **Tree failures after original Survey (Trees #98, 103, 170, 171, 233, 237)**	**6 Trees**
APPRAISED VALUE-OAK TREE REMOVALS (Per Plan)	**$ 564,594.**
HERITAGE OAK REMOVALS	**NONE**




Photo A shows the two additional removals. Oak #152 trunk is at left. Oak #153 trunk is on the right. Removal is due to grading.



Photo B shows partially defoliated Oak #152 due to drought stress.



Photo C shows branch tip dieback and dead branches in Oak #153.

BOB HANSEN© Tree Preservation

Registered Consulting Arborist #352

Certified Arborist #1142
CA #649218

September 5, 2006

ADDENDUM

Name: The Master's College
Address: 21726 Placerita Canyon Road
City: Santa Clarita, California 91321

Address of Project: 21726 Placerita Canyon Road

Mr. Hutton:

This is the addendum to the "Tree Report" with the date October 3, 2005. The addendum was requested by Mr. Gordon Jenewein.

This addendum reflects the necessary changes in the original tree report due to changes being made in the design of some portions of the project. This resulted in less oak trees being removed. Changes were also made in the in areas of "No Impact", and "Work Within Dripline". Also with less removals the total dollar amount for the appraised value of the trees needs to be adjusted.

Note:
Oak trees #152, #153, #176, #189, #239 are no longer listed as removals. The "TREE APPRAISAL" pages are enclosed for easy reference.
"New Summary Of Data" pages are enclosed with the necessary changes to correspond with the "Design Change Summary" that is also enclosed.

I hope this addendum is helpful in the forward movement of your project.

Respectfully submitted:

Robert Hansen, ASCA #352
ISA Certified Arborist #1142

7023 Semrad Road West Hills CA 91307

(818) 703-8024 Fax (818) 888-7954

MASTER'S COLLEGE OAK TREE DESIGN CHANGE SUMMARY
8/22/2006

Changes have been made to the following trees due to design changes.

Tree Numbers: 87, 88, 89, 125, 151, 152, 153, 176, 189, 232, 235, 236, 239, 240, 253, 254, 262, 263, 264, 267, 269, 272.

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
1	Quercus agrifolia	18"9"	x				
2	Quercus agrifolia	17"11"17"12"	x				
3 H.T	Quercus agrifolia	72"		x			Grading and retaining wall
4	Quercus agrifolia	4"	x				
5	Quercus agrifolia	11"9"			x		Grading
6	Quercus agrifolia	16"				x	Grading
7	Quercus agrifolia	9"				x	Grading
8	Quercus agrifolia	10"				x	Grading
9	Quercus agrifolia	20"				x	Grading
10	Quercus agrifolia	12"13"				x	Grading
11	Quercus agrifolia	13"10"7"				x	Grading
12	Quercus agrifolia	12"13"				x	Grading
13	Quercus agrifolia	20"13"				x	Grading Within Key
14	Quercus agrifolia	11"8"6"	x				
15 H. T	Quercus agrifolia	42"	x				
16	Quercus agrifolia	13"21"18"10"21"6"	x				
17	Quercus agrifolia	16"13"	x				
	SHEET 7 OF 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
18	Quercus agrifolia	20"	x				
19	Quercus agrifolia	15"	x				
20	Quercus agrifolia	17"	x				
21	Quercus agrifolia	22"	x				
22	Quercus agrifolia	13"	x				
23	Quercus agrifolia	7"6"6"	x				
24	Quercus agrifolia	10"7"6"	x				
25	Quercus agrifolia	12"	x				
26	Quercus agrifolia	19"15"10"	x				
27	Quercus agrifolia	10"8"			x		Grading
28	Quercus agrifolia	3"			x		Grading
29	Quercus agrifolia	5"3"			x		Grading
30	Quercus agrifolia	6"				x	Grading
31	Quercus agrifolia	11"12"8"				x	Grading
32	Quercus agrifolia	18"9"7"				x	Grading
33	Quercus agrifolia	19"				x	Grading
34	Quercus agrifolia	5"4"3"				x	Grading
35	Quercus agrifolia	9"	x				
36	Quercus agrifolia	13"14"13"15"	x				
37	Quercus agrifolia	6"6"4"	x				
38	Quercus agrifolia	4"	x				
39	Quercus agrifolia	14"11"12"12"13"10"13"	x				
40	Quercus agrifolia	13"	x				
41	Quercus agrifolia	9"	x				
42	Quercus agrifolia	11"8"	x				
43	Quercus agrifolia	20"19"14"	x				
44	Quercus agrifolia	25"14"	x				
45	Quercus agrifolia	20"8"	x				
46	Quercus berber.	3"4"4"4"3"3"	x				
47	Quercus agrifolia	9"	x				
48	Quercus agrifolia	19"22"14"	x				
49	Quercus agrifolia	22"19"	x				
50	Quercus agrifolia	6"	x				
51	Quercus agrifolia	23"20"	x				
52	Quercus agrifolia	16"15"10"	x				
53	Quercus agrifolia	15"13"6"	x				
54	Quercus agrifolia	20"	x				
55	Quercus agrifolia	7"4"	x				
56	Quercus agrifolia	42"11"	x				
57	Quercus agrifolia	6"6"4"3"3"	x				
351	Quercus berber.	2"2"2"2"2"2"3"3"				x	Grading
353	Quercus agrifolia	20"10"12"8"5"4"3"	x				
	SHEET 5 OF 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
58	Quercus agrifolia	4"				x	Grading
59	Quercus agrifolia	4"5				x	Grading
60	Quercus agrifolia	19"				x	Grading
61	Quercus agrifolia	15"16"				x	Grading
62	Quercus agrifolia	16"11"7"				x	Grading
63	Quercus agrifolia	17"				x	Grading
64	Quercus agrifolia	17"20"				x	Grading
65	Quercus agrifolia	11"				x	Grading
66	Quercus agrifolia	5"				x	Grading
67	Quercus agrifolia	17"15"				x	Grading
68	Quercus agrifolia	14"				x	Grading
69	Quercus agrifolia	10"				x	Grading
70	Quercus agrifolia	19"				x	Grading
71	Quercus agrifolia	22"				x	Grading
72	Quercus agrifolia	5"4"				x	Grading
73	Quercus agrifolia	12"				x	Grading
74	Quercus agrifolia	32"			x		Grading
75	Quercus agrifolia	9"			x		Grading
76	Quercus agrifolia	10"16"			x		Grading
77	Quercus agrifolia	18"17"7"			x		Grading
78	Quercus agrifolia	11"	x				
79	Quercus agrifolia	8"	x				
80	Quercus agrifolia	3"	x				
81	Quercus agrifolia	8"			x		Grading
82	Quercus agrifolia	13"			x		Grading
83	Quercus agrifolia	10"8"			x		Grading
84	Quercus agrifolia	4"4"3"2"			x		Grading
85	Quercus agrifolia	5"			x		Grading
86	Quercus agrifolia	8"			x		Grading
87	Quercus agrifolia	8"			x		Future Walk
88	Quercus agrifolia	11"			x		Future Walk
89	Quercus agrifolia	20"18"15"			x		Future Walk
90	Quercus agrifolia	20"15"			x		Grading
91	Quercus agrifolia	16"18"12"			x		Grading
92	Quercus agrifolia	6"			x		Grading
93	Quercus agrifolia	8"11"				x	Grading
94	Quercus agrifolia	16"8"16"26"				x	Grading
95	Quercus agrifolia	7"				x	Grading
96	Quercus agrifolia	16"13"				x	Grading
97	Quercus agrifolia	14"				x	Grading
98	Quercus agrifolia	16"				x	DEAD
99	Quercus agrifolia	10"8"				x	Grading
100	Quercus agrifolia	25"				x	Grading
101	Quercus agrifolia	21"20"12"10'				x	Grading

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
102	Quercus agrifolia	15"			x		Sewer, SD, Deck
103	Quercus agrifolia	22"				x	Dead
104	Quercus agrifolia	14"16"	x				
105	Quercus berber.	6"	x				
106	Quercus agrifolia	9"		x			Deck
107	Quercus agrifolia	9"5"			x		New Walk
108	Quercus agrifolia	24"			x		New Walk
109	Quercus agrifolia	18"		x			Sewer, SD, Deck
110	Quercus agrifolia	23"			x		Sewer, SD, Deck
111	Quercus agrifolia	12"17"14"14"	x				Sewer, SD, Deck
112	Quercus agrifolia	22"		x			Sewer, SD
113	Quercus agrifolia	11"8"		x			Sewer, SD
114	Quercus agrifolia	14"	x				
115	Quercus agrifolia	12"	x				
116	Quercus agrifolia	15"	x				
117	Quercus agrifolia	12"18"	x				
118	Quercus agrifolia	9"	x				
119	Quercus agrifolia	10"	x				
120	Quercus berber.	8"7"9"			x		Sewer. SD, Future Walk
121	Quercus agrifolia	6"			x		Future Walk
122	Quercus agrifolia	13"			x		Future Walk
123	Quercus agrifolia	17"15"			x		Future Walk
124	Quercus agrifolia	13"12"	x				
125	Quercus agrifolia	20"	x				Future Walk
128	Quercus agrifolia	4"4"3"2"	x				
129	Quercus agrifolia	14"	x				
130	Quercus agrifolia	10"			x		Grading
131	Quercus berber.	7"			x		Grading
132	Quercus agrifolia	18"4"			x		Grading
133	Quercus agrifolia	16"			x		Grading
134	Quercus agrifolia	8"7"			x		Grading
	Sheet 6 of 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
126	Quercus agrifolia	9"	x				
127	Quercus berber.	9"8"7"	x				
135	Quercus berber.	5"2"		x			Grading
136	Quercus berber.	8"7"	x				
137	Quercus agrifolia	14"	x				
138	Quercus agrifolia	15"11"	x				
139	Quercus berber.	6"	x				
140	Quercus berber.	7"	x				
141	Quercus agrifolia	6"	x				
142	Quercus agrifolia	17"	x				
143	Quercus agrifolia	13"		x			Grading
144	Quercus agrifolia	7"		x			Grading
145	Quercus berber.	5"5"		x			Grading
146	Quercus berber.	5"2"2"	x				
147	Quercus berber.	7"6"	x				
148	Quercus berber.	8"	x				
149	Quercus agrifolia	10"	x				
150	Quercus agrifolia	10"	x				
151	Quercus agrifolia	12"	x				
152	Quercus agrifolia	15"			x		Grading
153	Quercus agrifolia	15"			x		Grading
154	Quercus berber.	11"			x		Grading
155	Quercus berber.	5"		x			Retaining Wall
156	Quercus agrifolia	5"3"	x				
157	Quercus agrifolia	11"	x				
158	Quercus berber.	7"	x				
159	Quercus berber.	4"4"3"2"		x			Future Parking Lot
160	Quercus agrifolia	6"4"	x				
161	Quercus agrifolia	6"	x				
162	Quercus berber.	6"	x				
163	Quercus agrifolia	23"	x				
164	Quercus agrifolia	14"	x				
165	Quercus berber.	14"	x				
166	Quercus berber.	7"7"	x				
167	Quercus agrifolia	14"	x				
168	Quercus berber.	8"7"	x				
169	Quercus agrifolia	20"			x		Future Driveway
170	Quercus agrifolia	10"12"12"16"				x	Fell during storm
171	Quercus agrifolia	10"				x	Fell during storm
172	Quercus agrifolia	9"	x				
173	Quercus agrifolia	23"	x				
174	Quercus agrifolia	17"	x				
175	Quercus agrifolia	22"	x				
176	Quercus agrifolia	21"		x			Grading

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
177	Quercus agrifolia	14"13"				x	Grading
178	Quercus agrifolia	20"				x	Grading
179	Quercus agrifolia	15"15"				x	Grading
180	Quercus agrifolia	12:11"6"				x	Grading
181	Quercus agrifolia	5"		x			Grading
182	Quercus agrifolia	19"3"	x				
183	Quercus agrifolia	6"	x				
184	Quercus agrifolia	14"8"	x				
185	Quercus agrifolia	6"			x		Grading
186	Quercus agrifolia	14"13"			x		Grading
187	Quercus agrifolia	18"				x	Grading
188	Quercus agrifolia	12"				x	Grading
189	Quercus agrifolia	27"			x		Grading
190	Quercus agrifolia	14"13"13"	x				
191	Quercus agrifolia	24"14"		x			Grading
192	Quercus agrifolia	19"	x				
193	Quercus agrifolia	15"9"11"10"12"			x		Future Parking Lot
194	Quercus agrifolia	13"	x				
195	Quercus agrifolia	18"			x		Future Parking Lot
196	Quercus agrifolia	12"			x		Future Parking Lot
197	Quercus agrifolia	14"			x		Future Parking Lot
198	Quercus agrifolia.	21"			x		Future Parking Lot
199	Quercus agrifolia.	14"10"	x				
200	Quercus agrifolia	7"	x				
201	Quercus agrifolia	12"8"	x				
202	Quercus agrifolia	7"6"5"	x				
203	Quercus agrifolia	4"	x				
204	Quercus agrifolia	4"5"	x				
205	Quercus agrifolia	5"3"	x				
206	Quercus agrifolia	3"3"3"	x				
207	Quercus agrifolia	6"5"4"	x				
208	Quercus agrifolia	3"	x				
209	Quercus agrifolia	3"	x				
210	Quercus agrifolia	4"4"3"2"2"	x				
211	Quercus agrifolia	3"4"3"3"2"	x				
212	Quercus agrifolia	3"	x				
213	Quercus agrifolia	3"	x				
214	Quercus agrifolia	3"4"2"	x				
215	Quercus agrifolia	8"	x				
216	Quercus agrifolia	25"	x				
217	Quercus agrifolia	33"	x				
218	Quercus agrifolia	5"3"4"	x				
219	Quercus agrifolia	28"	x				
220	Quercus agrifolia	14"9"8"	x				

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
221	Quercus agrifolia	14"13"	x				
222 H.T	Quercus agrifolia	40"			x		Grading
223	Quercus agrifolia	18"15"			x		Grading
224	Quercus agrifolia	24"			x		Grading
225	Quercus agrifolia	28"	x				
226 H.T	Quercus agrifolia	48"	x				
227	Quercus agrifolia	22"	x				
228	Quercus agrifolia	20"	x				
229	Quercus agrifolia	22"	x				
230	Quercus agrifolia	19"	x				
231	Quercus agrifolia	14"	x				
232	Quercus agrifolia	27"			x		Access Road
233	Quercus agrifolia	11"				x	Dead
234	Quercus agrifolia	30"16"			x		Grading
235 H.T	Quercus agrifolia	35"			x		Access Road
236	Quercus agrifolia	28"			x		Grading
237	Quercus agrifolia	20"				x	Grading
238	Quercus agrifolia	29"27"			x		Grading
239	Quercus agrifolia	32"			x		Access Road
240 H.T	Quercus agrifolia	48"			x		Access Road
241	Quercus agrifolia	16"	x				
242	Quercus agrifolia.	14"	x				
243	Quercus agrifolia.	14"	x				
244 H.T	Quercus agrifolia	29"26"	x				
245 H.T	Quercus agrifolia	39"	x				
246 H.T	Quercus agrifolia	34"	x				
247	Quercus agrifolia	18"	x				
248	Quercus agrifolia	25"	x				
249	Quercus agrifolia	18"	x				
250	Quercus agrifolia	15"	x				
251	Quercus agrifolia	19"9"	x				
252	Quercus agrifolia	10"8"8"7"	x				
253	Quercus agrifolia	19"			x		Future Walk
254	Quercus agrifolia	7"			x		Future Walk
255 H.T	Quercus agrifolia	45"	x				
256	Quercus agrifolia	9"	x				
257	Quercus agrifolia	30"	x				
258 H.T	Quercus agrifolia	54"	x				
259 H.T	Quercus agrifolia	66"	x				
260 H.T	Quercus agrifolia	38"	x				
261	Quercus agrifolia	32"	x				
262 H.T	Quercus agrifolia	32"22"			x		
263	Quercus agrifolia	21"			x		
264	Quercus agrifolia	21"21"17"19"			x		

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
265	Quercus agrifolia	22"	x				
266 H.T	Quercus agrifolia	34"			x		Future Walk, SD. Sewer
267	Quercus agrifolia	24"21"21"			x		Future Arbor
268	Quercus agrifolia	30"20"19"			x		Future Walk, SD.Sewer
269	Quercus agrifolia	17"			x		Future Walk
270 H.T	Quercus agrifolia	42"	x				
271	Quercus agrifolia	17"15"	x				
272	Quercus agrifolia	20"			x		Future Walk
273	Quercus agrifolia	24"			x		Futrure Walk
274 H.T	Quercus agrifolia	35"27"			x		Future Walk
275	Quercus agrifolia	22"			x		Future Walk
276	Quercus agrifolia	14"	x				
277	Quercus agrifolia	25"	x				
	SHEET 3 OF 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
278	Quercus agrifolia	30"20	x				
279	Quercus agrifolia	3"		x			Future Parking Lot
280 H.T	Quercus agrifolia	35"30"	x				
281	Quercus agrifolia	29"15"	x				
282 H. T	Quercus agrifolia	32"34"	x				
283	Quercus agrifolia	19"18"	x				
284	Quercus agrifolia	22"19"18"13"	x				
285	Quercus agrifolia	8"6"5"6"		x			Future Parking Lot
286	Quercus agrifolia	3"2"2"			x		Future Parking Lot
287	Quercus agrifolia	19"18"			x		Future Parking Lot
288 H. T	Quercus agrifolia	38"	x				
289 H. T	Quercus agrifolia	36"34"	x				
290	Quercus agrifolia	20"	x				
291	Quercus agrifolia	21"20"19"14"	x				
292 H. T	Quercus agrifolia	38"	x				
293	Quercus agrifolia	10"	x				
294	Quercus agrifolia	7"	x				
295	Quercus agrifolia	9"8"	x				
296	Quercus agrifolia	18"	x				
297	Quercus agrifolia	9"9"7"6"8"	x				
298	Quercus agrifolia	7"6"6"6"6"	x				
299	Quercus agrifolia.	4"	x				
300	Quercus agrifolia.	7"6"	x				
301	Quercus agrifolia	16"16"	x				
302	Quercus agrifolia	18"	x				
303	Quercus agrifolia	28"	x				
304	Quercus agrifolia	12"	x				
305	Quercus agrifolia	4"	x				
306	Quercus agrifolia	17"	x				
307	Quercus agrifolia	7"	x				
308	Quercus agrifolia	8"7"	x				
309	Quercus agrifolia	14"			x		Pedestrian Walk
310	Quercus agrifolia	8"			x		Pedestrian Walk
311	Quercus agrifolia	10"			x		Pedestrian Walk
312	Quercus agrifolia	9"			x		Pedestrian Walk
313	Quercus agrifolia	18"		x			Pedestrian Walk
314	Quercus agrifolia	5"4"		x			Pedestrian Walk
315	Quercus agrifolia	5"		x			Pedestrian Walk
316	Quercus agrifolia	10"			x		Pedestrian Walk
317	Quercus agrifolia	8"		x			Pedestrian Walk
318	Quercus agrifolia	7"6"	x				
319	Quercus agrifolia	7"3"	x				
320	Quercus agrifolia	8"	x				
	Sheet 6 of 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
321	Quercus agrifolia	8"7"		x			Pedestrian Walk
322	Quercus agrifolia	5"		x			Pedestrian Walk
323 H. T	Quercus agrifolia	32"32"19"			x		Pedestrian Walk
324 H. T	Quercus agrifolia	38"	x				
325	Quercus agrifolia	20"			x		Future Walk
	Sheet 6 0f 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
326	Quercus agrifolia	33"	x				
327 H.T	Quercus agrifolia	63"	x				
328	Quercus agrifolia	18"15"	x				
329 H.T	Quercus agrifolia	30"29"	x				
330 H.T	Quercus agrifolia	26"24"23"	x				
331 H.T	Quercus agrifolia	37"	x				
332 H.T	Quercus agrifolia	34"	x				
333 H.T	Quercus agrifolia	35"	x				
334	Quercus agrifolia	36"20"17"20"	x				
335 H.T	Quercus agrifolia	32"28"	x				
336	Quercus agrifolia	24"19"	x				
337 H.T	Quercus agrifolia	70"	x				
338	Quercus agrifolia	30"	x				
339	Quercus agrifolia	23"	x				
340	Quercus agrifolia	19"12"11"8"17"	x				
341 H.T	Quercus agrifolia	39"	x				
342	Quercus agrifolia	25"	x				
343 H.T	Quercus agrifolia	25"29"18"	x				
344	Quercus agrifolia	22"17"14"	x				
345	Quercus agrifolia	18"15"14"8"	x				
346	Quercus agrifolia	24"19"15"	x				
347	Quercus agrifolia	20"19"	x				
348	Quercus agrifolia	22"20"24"	x				
349 H.T	Quercus agrifolia	58"	x				
350	Quercus agrifolia	32"	x				
	SHEET 2 OF 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
352	Quercus agrifolia	6"4"3"3"2"				x	Grading
	SHEET 4 OF 7						

TREE APPRAISAL

TREE NUMBER	152
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION		70%				
TRUNK DIAMETER		15	SITE	CONT.	PLACE	
LOCATION			80%	70%	70%	73%
SPECIES RATING		90%				
REPLACEMENT TREE SIZE		5.50	23.75			
REPLACEMENT TREE COST		$1,482.00				
INSTALLATION COST		$1,482.00				
INSTALLED TREE COST		$2,964.00				
UNIT TREE COST		$62.40				
APPRAISED TRUNK AREA	176.63	177				
APPRAISED TREE TRUNK INCREASE		153				
BASIC TREE COST		$12,526.80				
APPRAISED VALUE		**$5,787.38**				

TREE APPRAISAL

TREE NUMBER	153
ROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION		70%				
TRUNK DIAMETER		15	SITE	CONT.	PLACE	
LOCATION			80%	70%	70%	73%
SPECIES RATING		90%				
REPLACEMENT TREE SIZE		5.50	23.75			
REPLACEMENT TREE COST		$1,482.00				
INSTALLATION COST		$1,482.00				
INSTALLED TREE COST		$2,964.00				
UNIT TREE COST		$62.40				
APPRAISED TRUNK AREA	176.63	177				
APPRAISED TREE TRUNK INCREASE		153				
BASIC TREE COST		$12,526.80				
APPRAISED VALUE		**$5,787.38**				

TREE NUMBER	176
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION		70%				
TRUNK DIAMETER		21	SITE	CONT.	PLACE	
LOCATION			80%	70%	70%	73%
SPECIES RATING		90%				
REPLACEMENT TREE SIZE		5.50	23.75			
REPLACEMENT TREE COST		$1,482.00				
INSTALLATION COST		$1,482.00				
INSTALLED TREE COST		$2,964.00				
UNIT TREE COST		$62.40				
APPRAISED TRUNK AREA	346.19	346				
APPRAISED TREE TRUNK INCREASE		322				
BASIC TREE COST		$23,072.40				
APPRAISED VALUE		**$10,659.45**				

TREE APPRAISAL

TREE NUMBER	189
ROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION		60%				
TRUNK DIAMETER		24	SITE	CONT.	PLACE	
LOCATION			80%	70%	70%	73%
SPECIES RATING		90%				
REPLACEMENT TREE SIZE		5.50	23.75			
REPLACEMENT TREE COST		$1,482.00				
INSTALLATION COST		$1,482.00				
INSTALLED TREE COST		$2,964.00				
UNIT TREE COST		$62.40				
APPRAISED TRUNK AREA	452.16	452				
APPRAISED TREE TRUNK INCREASE		428				
BASIC TREE COST		$29,686.80				
APPRAISED VALUE		**$11,755.97**				

TREE NUMBER	239
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION		70%				
TRUNK DIAMETER		32	SITE	CONT.	PLACE	
LOCATION			80%	70%	70%	73%
SPECIES RATING		90%				
REPLACEMENT TREE SIZE		5.50	23.75			
REPLACEMENT TREE COST		$1,482.00				
INSTALLATION COST		$1,482.00				
INSTALLED TREE COST		$2,964.00				
UNIT TREE COST		$62.40				
APPRAISED TRUNK AREA	803.84	804	ATA			
APPRAISED TREE TRUNK INCREASE		780				
BASIC TREE COST		$51,651.60				
APPRAISED VALUE		**$23,863.04**				

OAK TREE REPORT

VOLUME I

Project Location:
The Master's College
21726 Placerita Canyon Road
Santa Clarita, CA 91321

Prepared for:
Mr. Robert L. Hotton
The Master's College
21726 Placerita Canyon Road
Santa Clarita, CA 91321

And
Mr. Gordon Jenewein
Development Planning Services
651 Via Alondra, Suite 711
Camarillo, CA 93012
Tel 805 484-8303

October 3, 2005

Report Submitted By:
ROBERT HANSEN, ASCA
Registered Consulting Arborist #352
7023 Semrad Road
West Hills CA 91307
Tel. 818 703-8024

And
CRAIG CROTTY
ARBOR CULTURE
ASCA, Member
P.O. Box 246
Verdugo City, CA 91046
Direct 818 636-4917
Office 818 957-8824

CONTENTS

Introduction Section 1

Summary of Data Section 2

Summary of Visual Field Inspection-Oak Trees Section 3

Recommendations for Oak Trees Located over High-Frequency Use Areas Section 4
(Pre-Existing Conditions Unrelated to Proposed Construction)

Recommendation to Reduce Impact on Oak Trees During Construction Section 5

General Recommendations for Oak Tree Maintenance Section 6

Signatures and Attachment List

- Assumptions and Limiting Conditions
- Curriculum Vitae (2)
- Tree Plan

Volume II Contents

- Appraisals
- Field Data Sheets
- Photographs

INTRODUCTION

The Master's College
21726 Placerita Canyon Road
Santa Clarita, CA 91321

INTRODUCTION

This Oak Tree Report is prepared on behalf of The Master's College, owner and applicant of the proposed educational, residential, and public thoroughfare development of a portion of Lot 1 of the St. john subdivision, Rancho San Francisco, in the City of Los Angeles, County of Los Angeles, State of California, as per map recorded in Book 196, Page (s) 304 seq. of miscellaneous records, in the Office of the County Recorder of said County.

The proposal includes addition of buildings, residences, roads, walks and other amenities consistent with a college campus and residential development. The proposed construction requires some grading and excavation for slope retention, roadways, retaining walls, underground services, etc. within Oak Tree Protection Zones.

The site is situated on both sloping and flat terrain. The slopes consist of a ridgeline that extends westerly from an existing single-family residential neighborhood, flanked on the north by existing buildings of The Master's College and to the south by a seasonal wash, known as the Newhall Creek. The hilly slopes are covered mostly with brush on undeveloped terrain, with some Oak trees located primarily in the canyons. The flat terrain is located on the north side of the project, near Placerita Canyon Road, and consists of current college facilities, playing fields, parking lots and surrounding residential properties. There are many large Oak trees throughout the flat terrain section of the property.

A total of 353 Oak trees, *Quercus species*, were identified and tagged on this property. Two hundred eleven of these trees will not be impacted in any way by the proposal. A total of 56 trees would be removed due to the proposed construction. Eighty six Oaks will be impacted in various degrees by work proposed within the Tree Protection Zone (five feet beyond the dripline). No Heritage Oaks would be removed due to the proposal. Heritage Oak trees are trees with a trunk diameter of 34.4 inches and larger, or in the case of a multi-trunk, with at least two trunks of 22.9 inches each or greater.

Also, there are a number of Oak trees near human-use areas with pre-existing conditions, unrelated to the proposed development, identified and listed in Section 4. These Oaks have defects posing risks to people and property. Various treatments such as crown reduction pruning, support cabling, and even removal of the tree may be recommended to reduce some of these risks.

Section 5 lists recommendations to reduce impact on Oak trees during construction. Section 6 has general Oak tree maintenance recommendations. Relocation of Oak trees proposed for removal was not seen as a viable alternative when compared to purchasing new replacement trees of good condition and appropriate sizes. Any Oak trees to be removed due to proposed construction will be mitigated per the direction of City of Santa Clarita representatives from the City Planning Department and/or the City Oak Tree Specialist.

ORDINANCE AND GUIDELINES

Oak Trees within the City of Santa Clarita are considered a valuable aesthetic and ecological contributor to the quality of life and welfare of the community. The health and well being of the indigenous Oaks is protected by City Ordinance. Potentially harmful construction activity, along with other activities, is limited and delineated by the Ordinance.

Oak Tree Guidelines describes tree protection zones of 5 feet beyond the dripline or 15 feet from tree trunks for trees over two inches in diameter at 4.5 feet above grade. The applicant/developer of the project should obtain a copy of the City of Santa Clarita Oak Tree ordinance and guidelines and be familiar with conditions and requirements stated therein. A breach of the Oak Tree ordinance during any site work may result in stop work orders, citations, and suspension of building permits.

JUSTIFICATION STATEMENT

Justification for planned removal and encroachment of protected Oak trees would prohibit reasonable and conforming use of this property. Oak trees to be preserved on the site will be fenced off from harmful construction practices at the edge of the tree protection zone or at the limit of approved construction encroachment. Construction near Oak trees to remain will be monitored by the project Oak Tree Consultant to help insure the least detrimental impacts to the trees. A more detailed account of tree protection measures is found in Section 5-Recommendations to Reduce Impact on Oak Trees During Construction of this report.

SCOPE OF REPORT

This report includes field observations, descriptions, photos and surveyed locations of affected indigenous Oak trees. A seven page Tree Plan is included. Oak trees and parts within the site are physically measured and rated for overall condition.

ENVIRONMENTAL SITUATION

The vast majority of trees discussed in this report are Coast Live Oaks (*Quercus agrifolia*) with a few Scrub Oaks (*Quercus berberidifolia*). The Coast Live Oaks have considerable variation in age, size, health and structure. The Scrub Oak trees are smaller, shrubbier trees for the most part. Individual data for all the trees is located in the Field Data Sheets for each tree or group of trees.

SECTION 2

Summary of Data

IMPACT SUMMARY:	
TOTAL OAK TREES	**353 Trees**
OAK TREES NOT IMPACTED	**211 Trees**
ENCROACHMENT within the outer Five Feet Tree Protection Zone	**26 Trees**
ENCROACHMENT within OAK DRIPLINE	**60 Trees**
TOTAL OAK TREE REMOVALS	**56 Trees**
HERITAGE OAK REMOVALS	**NONE**

Note: The following 12 pages of Section 2 list all of the 353 Oak trees on the site. Descriptions of impacts are listed for each tree. Trees are grouped on the list corresponding to their appearance on each of seven sheets of the Tree Plan.

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
1	Quercus agrifolia	18"9"	x				
2	Quercus agrifolia	17"11"17"12"	x				
3 H.T	Quercus agrifolia	72"		x			Grading and retaining wall
4	Quercus agrifolia	4"	x				
5	Quercus agrifolia	11"9"			x		Grading
6	Quercus agrifolia	16"				x	Grading
7	Quercus agrifolia	9"				x	Grading
8	Quercus agrifolia	10"				x	Grading
9	Quercus agrifolia	20"				x	Grading
10	Quercus agrifolia	12"13"				x	Grading
11	Quercus agrifolia	13"10"7"				x	Grading
12	Quercus agrifolia	12"13"				x	Grading
13	Quercus agrifolia	20"13"				x	Grading Within Key
14	Quercus agrifolia	11"8"6"	x				
15 H. T	Quercus agrifolia	42"	x				
16	Quercus agrifolia	13"21"18"10"21"6"	x				
17	Quercus agrifolia	16"13"	x				
	SHEET 7 OF 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
18	Quercus agrifolia	20"	x				
19	Quercus agrifolia	15"	x				
20	Quercus agrifolia	17"	x				
21	Quercus agrifolia	22"	x				
22	Quercus agrifolia	13"	x				
23	Quercus agrifolia	7"6"6"	x				
24	Quercus agrifolia	10"7"6"	x				
25	Quercus agrifolia	12"	x				
26	Quercus agrifolia	19"15"10"	x				
27	Quercus agrifolia	10"8"			x		Grading
28	Quercus agrifolia	3"			x		Grading
29	Quercus agrifolia	5"3"			x		Grading
30	Quercus agrifolia	6"				x	Grading
31	Quercus agrifolia	11"12"8"				x	Grading
32	Quercus agrifolia	18"9"7"				x	Grading
33	Quercus agrifolia	19"				x	Grading
34	Quercus agrifolia	5"4"3"				x	Grading
35	Quercus agrifolia	9"	x				
36	Quercus agrifolia	13"14"13"15"	x				
37	Quercus agrifolia	6"6"4"	x				
38	Quercus agrifolia	4"	x				
39	Quercus agrifolia	14"11"12"12"13"10"13"	x				
40	Quercus agrifolia	13"	x				
41	Quercus agrifolia	9"	x				
42	Quercus agrifolia	11"8"	x				
43	Quercus agrifolia	20"19"14"	x				
44	Quercus agrifolia	25"14"	x				
45	Quercus agrifolia	20"8"	x				
46	Quercus berber.	3"4"4"4"3"3"	x				
47	Quercus agrifolia	9"	x				
48	Quercus agrifolia	19"22"14"	x				
49	Quercus agrifolia	22"19"	x				
50	Quercus agrifolia	6"	x				
51	Quercus agrifolia	23"20"	x				
52	Quercus agrifolia	16"15"10"	x				
53	Quercus agrifolia	15"13"6"	x				
54	Quercus agrifolia	20"	x				
55	Quercus agrifolia	7"4"	x				
56	Quercus agrifolia	42"11"	x				
57	Quercus agrifolia	6"6"4"3"3"	x				
351	Quercus berber.	2"2"2"2"2"2"3"3"				x	Grading
353	Quercus agrifolia	20"10"12"8"5"4"3"	x				
	SHEET 5 OF 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
58	Quercus agrifolia	4"				x	Grading
59	Quercus agrifolia	4"5				x	Grading
60	Quercus agrifolia	19"				x	Grading
61	Quercus agrifolia	15"16"				x	Grading
62	Quercus agrifolia	16"11"7"				x	Grading
63	Quercus agrifolia	17"				x	Grading
64	Quercus agrifolia	17"20"				x	Grading
65	Quercus agrifolia	11"				x	Grading
66	Quercus agrifolia	5"				x	Grading
67	Quercus agrifolia	17"15"				x	Grading
68	Quercus agrifolia	14"				x	Grading
69	Quercus agrifolia	10"				x	Grading
70	Quercus agrifolia	19"				x	Grading
71	Quercus agrifolia	22"				x	Grading
72	Quercus agrifolia	5"4"				x	Grading
73	Quercus agrifolia	12"				x	Grading
74	Quercus agrifolia	32"			x		Grading
75	Quercus agrifolia	9"			x		Grading
76	Quercus agrifolia	10"16"			x		Grading
77	Quercus agrifolia	18"17"7"			x		Grading
78	Quercus agrifolia	11"	x				
79	Quercus agrifolia	8"	x				
80	Quercus agrifolia	3"	x				
81	Quercus agrifolia	8"			x		Grading
82	Quercus agrifolia	13"			x		Grading
83	Quercus agrifolia	10"8"			x		Grading
84	Quercus agrifolia	4"4"3"2"			x		Grading
85	Quercus agrifolia	5"			x		Grading
86	Quercus agrifolia	8"			x		Grading
87	Quercus agrifolia	8"	x				
88	Quercus agrifolia	11"	x				
89	Quercus agrifolia	20"18"15"	x				
90	Quercus agrifolia	20"15"			x		Grading
91	Quercus agrifolia	16"18"12"			x		Grading
92	Quercus agrifolia	6"			x		Grading
93	Quercus agrifolia	8"11"				x	Grading
94	Quercus agrifolia	16"8"16"26"				x	Grading
95	Quercus agrifolia	7"				x	Grading
96	Quercus agrifolia	16"13"				x	Grading
97	Quercus agrifolia	14"				x	Grading
98	Quercus agrifolia	16"				x	DEAD
99	Quercus agrifolia	10"8"				x	Grading
100	Quercus agrifolia	25"				x	Grading
101	Quercus agrifolia	21"20"12"10'				x	Grading

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
102	Quercus agrifolia	15"			x		Sewer, SD, Deck
103	Quercus agrifolia	22"				x	Dead
104	Quercus agrifolia	14"16"	x				
105	Quercus berber.	6"	x				
106	Quercus agrifolia	9"		x			Deck
107	Quercus agrifolia	9"5"			x		New Walk
108	Quercus agrifolia	24"			x		New Walk
109	Quercus agrifolia	18"		x			Sewer, SD, Deck
110	Quercus agrifolia	23"			x		Sewer, SD, Deck
111	Quercus agrifolia	12"17"14"14"	x				Sewer, SD, Deck
112	Quercus agrifolia	22"		x			Sewer, SD
113	Quercus agrifolia	11"8"		x			Sewer, SD
114	Quercus agrifolia	14"	x				
115	Quercus agrifolia	12"	x				
116	Quercus agrifolia	15"	x				
117	Quercus agrifolia	12"18"	x				
118	Quercus agrifolia	9"	x				
119	Quercus agrifolia	10"	x				
120	Quercus berber.	8"7"9"			x		Sewer. SD, Future Walk
121	Quercus agrifolia	6"			x		Future Walk
122	Quercus agrifolia	13"			x		Future Walk
123	Quercus agrifolia	17"15"			x		Future Walk
124	Quercus agrifolia	13"12"	x				
125	Quercus agrifolia	20"			x		Future Walk
128	Quercus agrifolia	4"4"3"2"	x				
129	Quercus agrifolia	14"	x				
130	Quercus agrifolia	10"			x		Grading
131	Quercus berber.	7"			x		Grading
132	Quercus agrifolia	18"4"			x		Grading
133	Quercus agrifolia	16"			x		Grading
134	Quercus agrifolia	8"7"			x		Grading
	Sheet 6 of 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
126	Quercus agrifolia	9"	x				
127	Quercus berber.	9"8"7"	x				
135	Quercus berber.	5"2"		x			Grading
136	Quercus berber.	8"7"	x				
137	Quercus agrifolia	14"	x				
138	Quercus agrifolia	15"11"	x				
139	Quercus berber.	6"	x				
140	Quercus berber.	7"	x				
141	Quercus agrifolia	6"	x				
142	Quercus agrifolia	17"	x				
143	Quercus agrifolia	13"		x			Grading
144	Quercus agrifolia	7"		x			Grading
145	Quercus berber.	5"5"		x			Grading
146	Quercus berber.	5"2"2"	x				
147	Quercus berber.	7"6"	x				
148	Quercus berber.	8"	x				
149	Quercus agrifolia	10"	x				
150	Quercus agrifolia	10"	x				
151	Quercus agrifolia	12"		x			Retaining Wall
152	Quercus agrifolia	15"				x	Grading
153	Quercus agrifolia	15"				x	Grading
154	Quercus berber.	11"			x		Grading
155	Quercus berber.	5"		x			Retaining Wall
156	Quercus agrifolia	5"3"	x				
157	Quercus agrifolia	11"	x				
158	Quercus berber.	7"	x				
159	Quercus berber.	4"4"3"2"		x			Future Parking Lot
160	Quercus agrifolia	6"4"	x				
161	Quercus agrifolia	6"	x				
162	Quercus berber.	6"	x				
163	Quercus agrifolia	23"	x				
164	Quercus agrifolia	14"	x				
165	Quercus berber.	14"	x				
166	Quercus berber.	7"7"	x				
167	Quercus agrifolia	14"	x				
168	Quercus berber.	8"7"	x				
169	Quercus agrifolia	20"			x		Future Driveway
170	Quercus agrifolia	10"12"12"16"				x	Fell during storm
171	Quercus agrifolia	10"				x	Fell during storm
172	Quercus agrifolia	9"	x				
173	Quercus agrifolia	23"	x				
174	Quercus agrifolia	17"	x				
175	Quercus agrifolia	22"	x				
176	Quercus agrifolia	21"		x		x	Grading

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
177	Quercus agrifolia	14"13"				x	Grading
178	Quercus agrifolia	20"				x	Grading
179	Quercus agrifolia	15"15"				x	Grading
180	Quercus agrifolia	12:11"6"				x	Grading
181	Quercus agrifolia	5"		x			Grading
182	Quercus agrifolia	19"3"	x				
183	Quercus agrifolia	6"	x				
184	Quercus agrifolia	14"8"	x				
185	Quercus agrifolia	6"			x		Grading
186	Quercus agrifolia	14"13"			x		Grading
187	Quercus agrifolia	18"				x	Grading
188	Quercus agrifolia	12"				x	Grading
189	Quercus agrifolia	27"				x	Grading
190	Quercus agrifolia	14"13"13"	x				
191	Quercus agrifolia	24"14"		x			Grading
192	Quercus agrifolia	19"	x				
193	Quercus agrifolia	15"9"11"10"12"			x		Future Parking Lot
194	Quercus agrifolia	13"	x				
195	Quercus agrifolia	18"			x		Future Parking Lot
196	Quercus agrifolia	12"			x		Future Parking Lot
197	Quercus agrifolia	14"			x		Future Parking Lot
198	Quercus agrifolia.	21"			x		Future Parking Lot
199	Quercus agrifolia.	14"10"	x				
200	Quercus agrifolia	7"	x				
201	Quercus agrifolia	12"8"	x				
202	Quercus agrifolia	7"6"5"	x				
203	Quercus agrifolia	4"	x				
204	Quercus agrifolia	4"5"	x				
205	Quercus agrifolia	5"3"	x				
206	Quercus agrifolia	3"3"3"	x				
207	Quercus agrifolia	6"5"4"	x				
208	Quercus agrifolia	3"	x				
209	Quercus agrifolia	3"	x				
210	Quercus agrifolia	4"4"3"2"2"	x				
211	Quercus agrifolia	3"4"3"3"2"	x				
212	Quercus agrifolia	3"	x				
213	Quercus agrifolia	3"	x				
214	Quercus agrifolia	3"4"2"	x				
215	Quercus agrifolia	8"	x				
216	Quercus agrifolia	25"	x				
217	Quercus agrifolia	33"	x				
218	Quercus agrifolia	5"3"4"	x				
219	Quercus agrifolia	28"	x				
220	Quercus agrifolia	14"9"8"	x				

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
221	Quercus agrifolia	14"13"	x				
222 H.T	Quercus agrifolia	40"			x		Grading
223	Quercus agrifolia	18"15"			x		Grading
224	Quercus agrifolia	24"			x		Grading
225	Quercus agrifolia	28"	x				
226 H.T	Quercus agrifolia	48"	x				
227	Quercus agrifolia	22"	x				
228	Quercus agrifolia	20"	x				
229	Quercus agrifolia	22"	x				
230	Quercus agrifolia	19"	x				
231	Quercus agrifolia	14"	x				
232	Quercus agrifolia	27"		x			Grading
233	Quercus agrifolia	11"				x	Dead
234	Quercus agrifolia	30"16"			x		Grading
235 H.T	Quercus agrifolia	35"		x			Grading
236	Quercus agrifolia	28"		x			Grading
237	Quercus agrifolia	20"				x	Grading
238	Quercus agrifolia	29"27"			x		Grading
239	Quercus agrifolia	32"				x	Access Road
240 H.T	Quercus agrifolia	48"			x		Access Road
241	Quercus agrifolia	16"	x				
242	Quercus agrifolia.	14"	x				
243	Quercus agrifolia.	14"	x				
244 H.T	Quercus agrifolia	29"26"	x				
245 H.T	Quercus agrifolia	39"	x				
246 H.T	Quercus agrifolia	34"	x				
247	Quercus agrifolia	18"	x				
248	Quercus agrifolia	25"	x				
249	Quercus agrifolia	18"	x				
250	Quercus agrifolia	15"	x				
251	Quercus agrifolia	19"9"	x				
252	Quercus agrifolia	10"8"8"7"	x				
253	Quercus agrifolia	19"	x				
254	Quercus agrifolia	7"	x				
255 H.T	Quercus agrifolia	45"	x				
256	Quercus agrifolia	9"	x				
257	Quercus agrifolia	30"	x				
258 H.T	Quercus agrifolia	54"	x				
259 H.T	Quercus agrifolia	66"	x				
260 H.T	Quercus agrifolia	38"	x				
261	Quercus agrifolia	32"	x				
262 H.T	Quercus agrifolia	32"22"	x				
263	Quercus agrifolia	21"	x				
264	Quercus agrifolia	21"21"17"19"	x				

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
265	Quercus agrifolia	22"	x				
266 H.T	Quercus agrifolia	34"			x		Future Walk, SD. Sewer
267	Quercus agrifolia	24"21"21"	x				
268	Quercus agrifolia	30"20"19"			x		Future Walk, SD.Sewer
269	Quercus agrifolia	17"	x				
270 H.T	Quercus agrifolia	42"	x				
271	Quercus agrifolia	17"15"	x				
272	Quercus agrifolia	20"	x				
273	Quercus agrifolia	24"			x		Futrure Walk
274 H.T	Quercus agrifolia	35"27"			x		Future Walk
275	Quercus agrifolia	22"			x		Future Walk
276	Quercus agrifolia	14"	x				
277	Quercus agrifolia	25"	x				
	SHEET 3 OF 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
278	Quercus agrifolia	30"20	x				
279	Quercus agrifolia	3"		x			Future Parking Lot
280 H.T	Quercus agrifolia	35"30"	x				
281	Quercus agrifolia	29"15"	x				
282 H. T	Quercus agrifolia	32"34"	x				
283	Quercus agrifolia	19"18"	x				
284	Quercus agrifolia	22"19"18"13"	x				
285	Quercus agrifolia	8"6"5"6"		x			Future Parking Lot
286	Quercus agrifolia	3"2"2"			x		Future Parking Lot
287	Quercus agrifolia	19"18"			x		Future Parking Lot
288 H. T	Quercus agrifolia	38"	x				
289 H. T	Quercus agrifolia	36"34"	x				
290	Quercus agrifolia	20"	x				
291	Quercus agrifolia	21"20"19"14"	x				
292 H. T	Quercus agrifolia	38"	x				
293	Quercus agrifolia	10"	x				
294	Quercus agrifolia	7"	x				
295	Quercus agrifolia	9"8"	x				
296	Quercus agrifolia	18"	x				
297	Quercus agrifolia	9"9"7"6"8"	x				
298	Quercus agrifolia	7"6"6"6"6"	x				
299	Quercus agrifolia.	4"	x				
300	Quercus agrifolia.	7"6"	x				
301	Quercus agrifolia	16"16"	x				
302	Quercus agrifolia	18"	x				
303	Quercus agrifolia	28"	x				
304	Quercus agrifolia	12"	x				
305	Quercus agrifolia	4"	x				
306	Quercus agrifolia	17"	x				
307	Quercus agrifolia	7"	x				
308	Quercus agrifolia	8"7"	x				
309	Quercus agrifolia	14"			x		Pedestrian Walk
310	Quercus agrifolia	8"			x		Pedestrian Walk
311	Quercus agrifolia	10"			x		Pedestrian Walk
312	Quercus agrifolia	9"			x		Pedestrian Walk
313	Quercus agrifolia	18"		x			Pedestrian Walk
314	Quercus agrifolia	5"4"		x			Pedestrian Walk
315	Quercus agrifolia	5"		x			Pedestrian Walk
316	Quercus agrifolia	10"			x		Pedestrian Walk
317	Quercus agrifolia	8"		x			Pedestrian Walk
318	Quercus agrifolia	7"6"	x				
319	Quercus agrifolia	7"3"	x				
320	Quercus agrifolia	8"	x				
	Sheet 6 of 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
321	Quercus agrifolia	8"7"		x			Pedestrian Walk
322	Quercus agrifolia	5"		x			Pedestrian Walk
323 H. T	Quercus agrifolia	32"32"19"			x		Pedestrian Walk
324 H. T	Quercus agrifolia	38"	x				
325	Quercus agrifolia	20"			x		Future Walk
	Sheet 6 0f 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
326	Quercus agrifolia	33"	x				
327 H.T	Quercus agrifolia	63"	x				
328	Quercus agrifolia	18"15"	x				
329 H.T	Quercus agrifolia	30"29"	x				
330 H.T	Quercus agrifolia	26"24"23"	x				
331 H.T	Quercus agrifolia	37"	x				
332 H.T	Quercus agrifolia	34"	x				
333 H.T	Quercus agrifolia	35"	x				
334	Quercus agrifolia	36"20"17"20"	x				
335 H.T	Quercus agrifolia	32"28"	x				
336	Quercus agrifolia	24"19"	x				
337 H.T	Quercus agrifolia	70"	x				
338	Quercus agrifolia	30"	x				
339	Quercus agrifolia	23"	x				
340	Quercus agrifolia	19"12"11"8"17"	x				
341 H.T	Quercus agrifolia	39"	x				
342	Quercus agrifolia	25"	x				
343 H.T	Quercus agrifolia	25"29"18"	x				
344	Quercus agrifolia	22"17"14"	x				
345	Quercus agrifolia	18"15"14"8"	x				
346	Quercus agrifolia	24"19"15"	x				
347	Quercus agrifolia	20"19"	x				
348	Quercus agrifolia	22"20"24"	x				
349 H.T	Quercus agrifolia	58"	x				
350	Quercus agrifolia	32"	x				
	SHEET 2 OF 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
352	Quercus agrifolia	6"4"3"3"2"				x	Grading
	SHEET 4 OF 7						

SECTION 3


Summary of Visual Field Inspection-Oak Trees

In the following pages, individual trees are described in detail in the Visual Field Inspection Data Sheets for Trunk Diameter, Crown Size, Condition Ratings, Physical Characteristics, Horticultural Evaluation and Impact of Proposed Construction. Each of the 353 trees is identified by a number in the Visual Field Inspection Sheets which relates to a corresponding number on the Tree Plan and numbering tag affixed in the field.


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	1	2	3	4
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	18,9	17,11,17,12	72	4
HEIGHT (feet)	14	30	50	4
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				
2 WEAK MAIN CROTCH(ES)	x	x	x	
3 DEAD BRANCHES/TIP DECLINE		x	x	
4 CAVITY/WOUND ON TRUNK	x	x	x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x		x
REMOVE				
ENCROACHMENT INTO (TPZ)			x	
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)	x	x		
RATING				
OVERALL HEALTH	C	C	C	D
STRUCTURE	D	C	C	D
AESTHETICS/FORM	C	C	C	D
OVERALL CONDITION	**C**	**C**	**C**	**D**


TREE #1




TREE #2



TREE #3



TREE #4



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 1 Large cavity with decay in the base

TREE #

TREE # 3 Cavity in trunk

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	5	6	7	8
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	11,9	16	9	10
HEIGHT (feet)	34	38	28	32
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				
2 WEAK MAIN CROTCH(ES)	x	x	x	x
3 DEAD BRANCHES/TIP DECLINE	x	x		
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				
REMOVE		x	x	x
ENCROACHMENT INTO (TPZ)	x			
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	D	C	C	C
STRUCTURE	D	C	C	C
AESTHETICS/FORM	D	C	C	C
OVERALL CONDITION	**D**	**C**	**C**	**C**


TREE #5




TREE #6



TREE #7



TREE #8



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	9	10	11	12
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	20	16	13,10,7	12,13
HEIGHT (feet)	30	32	35	38
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	
2 WEAK MAIN CROTCH(ES)	x			x
3 DEAD BRANCHES/TIP DECLINE		x	x	x
4 CAVITY/WOUND ON TRUNK	x	x	x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				x
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				
REMOVE	x	x	x	x
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)	x			
MODERATE RISK (visible weak area)		x	x	
RATING				
OVERALL HEALTH	D	C	D	C
STRUCTURE	D	C	D	C
AESTHETICS/FORM	D	C	D	C
OVERALL CONDITION	**D**	**C**	**D**	**C**


TREE #9




TREE #10



TREE #11



TREE #12



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 9 Large cavity in trunk

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	13	14	15	16
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	10,13	11,8,6	42	12,19,18,10
HEIGHT (feet)	40	42	55	40
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING		x	x	x
2 WEAK MAIN CROTCH(ES)	x	x	x	x
3 DEAD BRANCHES/TIP DECLINE	x		x	x
4 CAVITY/WOUND ON TRUNK			x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE	x		x	x
8 DROUGHT STRESSED	x		x	x
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES			x	
11 FIRE DAMAGE				x
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)		x	x	x
REMOVE	x			
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)			x	x
RATING				
OVERALL HEALTH	C	D	C	C
STRUCTURE	C	D	C	D
AESTHETICS/FORM	C	D	C	D
OVERALL CONDITION	**C**	**D**	**C**	**C**


TREE #13




TREE #14



TREE #15



TREE #16



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE # 16 Large cavity in base

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	17	18	19	20
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	16,13	20	15	17
HEIGHT (feet)	28	52	24	22
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	x
2 WEAK MAIN CROTCH(ES)		x		x
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK	x	x	x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE	x	x	x	x
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES		x	x	x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)	x	x	x	x
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	D	D
STRUCTURE	D	C	D	D
AESTHETICS/FORM	C	C	D	D
OVERALL CONDITION	**C**	**C**	**D**	**D**


TREE #17




TREE #18



TREE #19



TREE #20



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 17 Large cavity in base

TREE #

TREE # 19 Large cavity in base

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	21	22	23	24
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	22	13	7,6,6	10,7,6
HEIGHT (feet)	38	26	22	20
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x			
2 WEAK MAIN CROTCH(ES)		x	x	x
3 DEAD BRANCHES/TIP DECLINE		x	x	x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES	x	x		
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x			
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	B	B	C
STRUCTURE	C	B	C	C
AESTHETICS/FORM	C	B	C	C
OVERALL CONDITION	**C**	**B**	**C**	**C**


TREE #21




TREE #22



TREE #23



TREE #24



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	25	26	27	28
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	12	19,15,10	10,8	3
HEIGHT (feet)	22	48	30	13
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x		x	
2 WEAK MAIN CROTCH(ES)		x	x	x
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE		x		
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE		x		
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x		
REMOVE				
ENCROACHMENT INTO (TPZ)			x	x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	D	B	C
STRUCTURE	C	D	B	C
AESTHETICS/FORM	C	D	B	C
OVERALL CONDITION	**C**	**D**	**B**	**C**


TREE #25




TREE #26



TREE #27



TREE #28



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	29	30	31	32
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	5,3	6	11,12,8	18,9,7
HEIGHT (feet)	17	28	28	30
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING		x		x
2 WEAK MAIN CROTCH(ES)			x	x
3 DEAD BRANCHES/TIP DECLINE		x	x	x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				x
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				x
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x		x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				
REMOVE		x	x	x
ENCROACHMENT INTO (TPZ)	x			
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE #29




TREE #30



TREE #31



TREE #32



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 30 Leans to N.E.

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	33	34	35	36
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	19	5,4,3	9	13,14,13,15
HEIGHT (feet)	34	10	28	42
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				x
2 WEAK MAIN CROTCH(ES)				x
3 DEAD BRANCHES/TIP DECLINE	x	x		x
4 CAVITY/WOUND ON TRUNK				x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)			x	x
REMOVE	x	x		
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	B	C	C	C
STRUCTURE	B	C	D	C
AESTHETICS/FORM	B	C	D	C
OVERALL CONDITION	**B**	**C**	**D**	**C**


TREE #33




TREE #34



TREE #35



TREE #36



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 35 Leans to the West

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	37	38	39	40
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	6,6,4	4	Multi	13
HEIGHT (feet)	19	18	36	28
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				x
2 WEAK MAIN CROTCH(ES)				x
3 DEAD BRANCHES/TIP DECLINE		x		
4 CAVITY/WOUND ON TRUNK				x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE #37




TREE #38



TREE #39



TREE #40



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 39 Multi 10,13,12,12,10,13,13

TREE # 40 Large cavity in trunk

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	41	42	43	44
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	9	11,8	27,10	25,14
HEIGHT (feet)	32	28	32	32
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	x
2 WEAK MAIN CROTCH(ES)			x	x
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK			x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	C	D
AESTHETICS/FORM	C	C	C	D
OVERALL CONDITION	**C**	**C**	**C**	**D**


TREE #41




TREE #42



TREE #43



TREE #44



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 43 Large cavity in trunk 27,16,7

TREE # 44 Large cavity in trunk - bees

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	45	46	47	48
SPECIES: *(Quercus agrifolia)*	x		x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	20,8	multi	9	28
HEIGHT (feet)	24	12	12	38
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING		x		
2 WEAK MAIN CROTCH(ES)	x			
3 DEAD BRANCHES/TIP DECLINE	x	x	x	
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	D	B	C
STRUCTURE	C	D	B	C
AESTHETICS/FORM	C	D	B	C
OVERALL CONDITION	**C**	**D**	**B**	**C**


TREE #45




TREE #46



TREE #47



TREE #48



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 46 (*Quercus berberidifolia*) 3,4,4,4,3,3

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	49	50	51	52
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	22,19	6	23,20	16,15,10
HEIGHT (feet)	39	14	38	38
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x		x	x
2 WEAK MAIN CROTCH(ES)			x	
3 DEAD BRANCHES/TIP DECLINE	x	x		x
4 CAVITY/WOUND ON TRUNK			x	
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				x
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES			x	x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE #49




TREE #50



TREE #51



TREE #52



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 49 Leaning West

TREE # 51 Large cavity in trunk

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	53	54	55	56
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	15,13,6	20	7,4	42,11
HEIGHT (feet)	36	39	18	50
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	x
2 WEAK MAIN CROTCH(ES)	x	x	x	x
3 DEAD BRANCHES/TIP DECLINE	x		x	x
4 CAVITY/WOUND ON TRUNK	x	x	x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE	x			
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES	x	x	x	x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x		x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				x
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				x
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE #53




TREE #54



TREE #55



TREE #56



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	57	58	59	60
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	6,6,4,3,3	4	4,5	19
HEIGHT (feet)	14	10	11	50
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x			
2 WEAK MAIN CROTCH(ES)				x
3 DEAD BRANCHES/TIP DECLINE	x			x
4 CAVITY/WOUND ON TRUNK				x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES	x	x	x	
11 FIRE DAMAGE			x	x
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x			
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x			
REMOVE		x	x	x
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	D	C
STRUCTURE	C	C	D	D
AESTHETICS/FORM	C	C	D	C
OVERALL CONDITION	**C**	**C**	**D**	**C**


TREE #57




TREE #58



TREE #59



TREE #60



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	61	62	63	64
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	15,16	16,11,7	17	17,20
HEIGHT (feet)	35	38	40	45
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING		x		x
2 WEAK MAIN CROTCH(ES)	x			x
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK	x			
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE	x			
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE	x	x	x	x
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				
REMOVE	x	x	x	x
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	D	C	D
STRUCTURE	D	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE #61




TREE #62



TREE #63



TREE #64



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	65	66	67	68
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	11	5	14,15	14
HEIGHT (feet)	38	14	50	18
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING			x	x
2 WEAK MAIN CROTCH(ES)	x	x	x	x
3 DEAD BRANCHES/TIP DECLINE				
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE	x	x	x	
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				
REMOVE	x	x	x	x
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE #65




TREE #66



TREE #67



TREE #68



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #


TREE #

TREE #


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	69	70	71	72
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	10	19	22	5,4
HEIGHT (feet)	15	35	45	14
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x		
2 WEAK MAIN CROTCH(ES)				
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE		x	x	
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				
REMOVE	x	x	x	x
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	D	C	C	C
STRUCTURE	D	C	C	C
AESTHETICS/FORM	D	C	C	C
OVERALL CONDITION	**D**	**C**	**C**	**C**


TREE #69




TREE #70



TREE #71



TREE #72



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	73	74	75	76
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	12	30	9	10,16
HEIGHT (feet)	33	65	20	30
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x			
2 WEAK MAIN CROTCH(ES)				
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK		x		
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE		x		
12 SOIL BUILDUP @ BASE	x			
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				
REMOVE	x			
ENCROACHMENT INTO (TPZ)		x	x	x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	D	C
STRUCTURE	C	B	D	C
AESTHETICS/FORM	C	B	D	C
OVERALL CONDITION	**C**	**B**	**D**	**C**


TREE #73




TREE #74



TREE #75



TREE #76



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	77	78	79	80
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	18,17,7	11	8	3
HEIGHT (feet)	42	24	28	10
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	
2 WEAK MAIN CROTCH(ES)	x			
3 DEAD BRANCHES/TIP DECLINE	x		x	x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)		x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)	x			
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE #77




TREE #78



TREE #79



TREE #80



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	81	82	83	84
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	8	13	10,8	4,4,3,2
HEIGHT (feet)	20	28	29	12
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				
2 WEAK MAIN CROTCH(ES)	x		x	x
3 DEAD BRANCHES/TIP DECLINE	x	x	x	
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE	x			
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				x
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x			
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				
REMOVE				
ENCROACHMENT INTO (TPZ)	x	x	x	x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE #81




TREE #82



TREE #83



TREE #84



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	85	86	87	88
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	5	8	8	11
HEIGHT (feet)	11	20	13	27
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				
2 WEAK MAIN CROTCH(ES)				
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)			x	x
REMOVE				
ENCROACHMENT INTO (TPZ)	x	x		
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	B	B
STRUCTURE	C	C	B	B
AESTHETICS/FORM	C	C	B	B
OVERALL CONDITION	**C**	**C**	**B**	**B**


TREE #85




TREE #86



TREE #87



TREE #88



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	89	90	91	92
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	20,18,15	20,15	19,18,12	6
HEIGHT (feet)	50	33	32	13
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING		x	x	
2 WEAK MAIN CROTCH(ES)	x		x	
3 DEAD BRANCHES/TIP DECLINE	x			x
4 CAVITY/WOUND ON TRUNK			x	
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES			x	
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x			
REMOVE				
ENCROACHMENT INTO (TPZ)		x	x	x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	B	C	C	C
STRUCTURE	B	C	C	C
AESTHETICS/FORM	B	C	C	C
OVERALL CONDITION	**B**	**C**	**C**	**C**


TREE #89




TREE #90



TREE #91



TREE #92



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	93	94	95	96
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	8,11	16,8,16,26	7	16,13
HEIGHT (feet)	28	50	25	30
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	x
2 WEAK MAIN CROTCH(ES)		x		
3 DEAD BRANCHES/TIP DECLINE	x	x		x
4 CAVITY/WOUND ON TRUNK	x			
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE	x			
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x		
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				
REMOVE	x	x	x	x
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	D
STRUCTURE	D	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE #93




TREE #94



TREE #95



TREE #96



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	97	98	99	100
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	14	16	10,8	25
HEIGHT (feet)	35	35	40	35
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	x
2 WEAK MAIN CROTCH(ES)				
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK				x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				x
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				x
13 RE-GROWTH FROM STUMP				x
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				
REMOVE	x	x	x	x
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	D
STRUCTURE	C	C	C	D
AESTHETICS/FORM	C	C	C	D
OVERALL CONDITION	**C**	**C**	**C**	**D**


TREE #97




TREE #98



TREE #99



TREE #100



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE # 98 This tree is dead and fell down

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	101	102	103	104
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	20,10,14,22	15	22	14,16
HEIGHT (feet)	50	35	40	47
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x			
2 WEAK MAIN CROTCH(ES)	x			
3 DEAD BRANCHES/TIP DECLINE		x	x	
4 CAVITY/WOUND ON TRUNK	x	x		
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK			x	
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE			x	x
12 SOIL BUILDUP @ BASE	x			
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				x
REMOVE	x		x	
ENCROACHMENT INTO (TPZ)		x		
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	D	D
STRUCTURE	C	C	D	D
AESTHETICS/FORM	C	C	D	D
OVERALL CONDITION	**C**	**C**	**D**	**D**


TREE #101




TREE #102



TREE #103



TREE #104



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE # 103 This tree is now dead

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	105	106	107	108
SPECIES: *(Quercus agrifolia)*		x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	6	9	95	24
HEIGHT (feet)	22	30	25	60
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING			x	x
2 WEAK MAIN CROTCH(ES)				
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK				x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK		x	x	
7 THIN FOLIAGE	x			
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE		x	x	
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION			x	x
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x			
REMOVE				
ENCROACHMENT INTO (TPZ)		x	x	x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	D	D	D	D
STRUCTURE	D	D	D	D
AESTHETICS/FORM	D	D	D	D
OVERALL CONDITION	**D**	**D**	**D**	**D**


TREE #105




TREE #106



TREE #107



TREE #108



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 105 (*Quercus berberidifolia*)

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	109	110	111	112
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	18	22	12,17,14,14	22
HEIGHT (feet)	55	55	50	48
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	x
2 WEAK MAIN CROTCH(ES)			x	x
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE	x	x	x	
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION	x	x		
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)			x	
REMOVE				
ENCROACHMENT INTO (TPZ)	x	x		x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	C	C	C	C


TREE #109




TREE #110



TREE #111



TREE #112



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	113	114	115	116
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	11,8	14	12	15
HEIGHT (feet)	30	25	33	25
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	x
2 WEAK MAIN CROTCH(ES)		x		
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK		x		x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE		x		x
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES	x	x		
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)		x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)	x			
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)		x		
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	D	C	C	C
AESTHETICS/FORM	D	C	C	C
OVERALL CONDITION	**D**	**C**	**C**	**C**


TREE #113




TREE #114



TREE #115



TREE #116



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 114 Major basal cavity

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	117	118	119	120
SPECIES: *(Quercus agrifolia)*	x	x	x	
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	12,18	9	10	8,7,9
HEIGHT (feet)	35	25	22	27
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	x
2 WEAK MAIN CROTCH(ES)	x			
3 DEAD BRANCHES/TIP DECLINE	x	x		x
4 CAVITY/WOUND ON TRUNK		x	x	
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES			x	
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	
REMOVE				
ENCROACHMENT INTO (TPZ)				x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	D	C
AESTHETICS/FORM	C	C	D	C
OVERALL CONDITION	**C**	**C**	**D**	**C**


TREE #117




TREE #118



TREE #119



TREE #120



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 120 (*Quercus berberidifolia*)

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	121	122	123	124
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	6	13	17,15	13,12
HEIGHT (feet)	18	35	30	38
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING			x	x
2 WEAK MAIN CROTCH(ES)				
3 DEAD BRANCHES/TIP DECLINE		x	x	x
4 CAVITY/WOUND ON TRUNK			x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES			x	x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION			x	
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				
REMOVE				
ENCROACHMENT INTO (TPZ)	x	x	x	x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	B	B	D	C
STRUCTURE	B	B	C	C
AESTHETICS/FORM	B	B	C	C
OVERALL CONDITION	**B**	**B**	**C**	**C**


TREE #121




TREE #122



TREE #123



TREE #124



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 124 Leaning on structure on the south east

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	125	126	127	128
SPECIES: *(Quercus agrifolia)*	x	x		x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	20	9	9,8,7	19
HEIGHT (feet)	22	24	28	40
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	x
2 WEAK MAIN CROTCH(ES)				
3 DEAD BRANCHES/TIP DECLINE			x	
4 CAVITY/WOUND ON TRUNK	x	x		
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED			x	
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES	x			x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)		x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)	x			
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)	x			
MODERATE RISK (visible weak area)				x
RATING				
OVERALL HEALTH	D	C	C	
STRUCTURE	D	C	C	
AESTHETICS/FORM	D	C	C	
OVERALL CONDITION	**D**	**C**	**C**	


TREE #125




TREE #126



TREE #127



TREE #128



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 125 Major cavity in co-dominant trunk

TREE # 127 (*Quercus berberidifolia*)

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	129	130	131	132
SPECIES: *(Quercus agrifolia)*	x	x		x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	14	10	7	18,4
HEIGHT (feet)	33	30	20	28
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING		x	x	x
2 WEAK MAIN CROTCH(ES)				
3 DEAD BRANCHES/TIP DECLINE				
4 CAVITY/WOUND ON TRUNK	x	x	x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				x
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x		x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION		x		
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x			
REMOVE				
ENCROACHMENT INTO (TPZ)		x	x	x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)		x		
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	D	C	C
STRUCTURE	C	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE #129




TREE #130



TREE #131



TREE #132



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 131 (Quercus berberidifolia)

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	133	134	135	136
SPECIES: *(Quercus agrifolia)*	x	x		
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	16	8,7	5,2	8,7
HEIGHT (feet)	25	22	12	25
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING		x	x	x
2 WEAK MAIN CROTCH(ES)				
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES		x		
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP		x		
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				x
REMOVE				
ENCROACHMENT INTO (TPZ)	x	x	x	
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	D	D	D	D
STRUCTURE	C	D	D	D
AESTHETICS/FORM	C	D	D	D
OVERALL CONDITION	**C**	**D**	**D**	**D**


TREE #133




TREE #134



TREE #135



TREE #136



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 135 (*Quercus berberidifolia*)

TREE # 136 (*Quercus berberidifolia*)

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	137	138	139	140
SPECIES: *(Quercus agrifolia)*	x	x		
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	14	15,15	6	7
HEIGHT (feet)	20	38	18	18
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x			
2 WEAK MAIN CROTCH(ES)	x			
3 DEAD BRANCHES/TIP DECLINE		x	x	x
4 CAVITY/WOUND ON TRUNK	x	x		
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK	x	x		
7 THIN FOLIAGE	x			
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)	x	x		
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	D	D	C	C
STRUCTURE	D	D	C	C
AESTHETICS/FORM	D	D	C	C
OVERALL CONDITION	**D**	**D**	**C**	**C**


TREE #137




TREE #138



TREE #139



TREE #140



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 137 Broken top - cavity in trunk

TREE # 138 Basal cavity

TREE # 139 (*Quercus berberidifolia*)

TREE # 140 (*Quercus berberidifolia*)

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	141	142	143	144
SPECIES: *(Quercus agrifolia)*		x	x	
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	6	17	13	7
HEIGHT (feet)	14	40	18	18
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	
2 WEAK MAIN CROTCH(ES)		x	x	
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK			x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK			x	
7 THIN FOLIAGE			x	
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES			x	
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING		x		
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x		
REMOVE				
ENCROACHMENT INTO (TPZ)			x	x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)			x	
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	D	C
STRUCTURE	C	C	D	C
AESTHETICS/FORM	C	C	D	C
OVERALL CONDITION	**C**	**C**	**D**	**C**


TREE #141




TREE #142



TREE #143



TREE #144



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 141 (*Quercus berberidifolia*)

TREE # 143 Cavity in main trunk - **severe risk of failing**

TREE # 144 (*Quercus berberidifolia*)

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	145	146	147	148
SPECIES: *(Quercus agrifolia)*		x		
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	5,5	5,2,3	7,6	8
HEIGHT (feet)	14	15	20	20
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x		
2 WEAK MAIN CROTCH(ES)		x		x
3 DEAD BRANCHES/TIP DECLINE	x		x	x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)		x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)	x			
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE #145




TREE #146



TREE #147



TREE #148



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 145 (*Quercus berberidifolia*)

TREE # 146 (*Quercus berberidifolia*)

TREE # 147 (*Quercus berberidifolia*)

TREE # 148 (*Quercus berberidifolia*)

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	149	150	151	152
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	10	10	12	15
HEIGHT (feet)	25	20	26	32
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x		
2 WEAK MAIN CROTCH(ES)			x	x
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK		x	x	
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED	x	x	x	
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING		x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x		
REMOVE				x
ENCROACHMENT INTO (TPZ)			x	
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)	x			
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	D	C	C
AESTHETICS/FORM	C	D	C	C
OVERALL CONDITION	**C**	**D**	**C**	**C**


TREE #149




TREE #150



TREE #151



TREE #152



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 150 Large cavity in trunk

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	153	154	155	156
SPECIES: *(Quercus agrifolia)*	x			x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	15	11	5	5,3
HEIGHT (feet)	30	22	16	18
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				
2 WEAK MAIN CROTCH(ES)				
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK	x	x		
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE	x			
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				x
REMOVE	x			
ENCROACHMENT INTO (TPZ)		x	x	
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE #153




TREE #154



TREE #155



TREE #156



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 154 (*Quercus berberidifolia*)

TREE # 155 (*Quercus berberidifolia*)

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	157	158	159	160
SPECIES: *(Quercus agrifolia)*	x			x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	11	7	4,4,3,2	6,4
HEIGHT (feet)	30	21	17	21
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x			
2 WEAK MAIN CROTCH(ES)				
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x		x
REMOVE				
ENCROACHMENT INTO (TPZ)			x	
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	D	C	C
STRUCTURE	C	D	C	C
AESTHETICS/FORM	C	D	C	C
OVERALL CONDITION	**C**	**D**	**C**	**C**


TREE #157




TREE #158



TREE #159



TREE #160



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 158 (*Quercus berberidifolia*)

TREE # 159 (*Quercus berberidifolia*)

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	161	162	163	164
SPECIES: *(Quercus agrifolia)*	x		x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	6	6	23	14
HEIGHT (feet)	20	19	35	28
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				x
2 WEAK MAIN CROTCH(ES)				
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK			x	
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE		x		
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	D	C	C
STRUCTURE	C	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE #161




TREE #162



TREE #163



TREE #164



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 162 (*Quercus berberidifolia*)

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	165	166	167	168
SPECIES: *(Quercus agrifolia)*	x		x	
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	14	7,7	14	8,7
HEIGHT (feet)	8	23	30	20
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING		x		
2 WEAK MAIN CROTCH(ES)	x			
3 DEAD BRANCHES/TIP DECLINE	x		x	x
4 CAVITY/WOUND ON TRUNK	x	x		
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP	x			
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	D	C	C	C
AESTHETICS/FORM	D	C	C	C
OVERALL CONDITION	**D**	**C**	**C**	**C**


TREE #165




TREE #166



TREE #167



TREE #168



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 166 (*Quercus berberidifolia*)

TREE # 168 (*Quercus berberidifolia*)

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	169	170	171	172
SPECIES: *(Quercus agrifolia)*	x	x		
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	20	10,11,15	10	9
HEIGHT (feet)	35	24	22	18
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING		x	x	x
2 WEAK MAIN CROTCH(ES)		x	x	
3 DEAD BRANCHES/TIP DECLINE	x	x		x
4 CAVITY/WOUND ON TRUNK		x		x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED		x	x	
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES		x		
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x			
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				x
REMOVE		x	x	
ENCROACHMENT INTO (TPZ)	x			
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	D
STRUCTURE	C	C	C	D
AESTHETICS/FORM	C	C	C	D
OVERALL CONDITION	**C**	**C**	**C**	**D**


TREE #169




TREE #170



TREE #171



TREE #172



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 170 The tree fell during the rains last winter and is now dead

TREE # 171 The tree fell during the rains last winter and is now dead

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	173	174	175	176
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	23	17	22	21
HEIGHT (feet)	35	26	40	31
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x		x
2 WEAK MAIN CROTCH(ES)				
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK	x			x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES			x	
11 FIRE DAMAGE	x	x	x	x
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	
REMOVE				
ENCROACHMENT INTO (TPZ)				x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	D	D	D	D
STRUCTURE	D	D	C	D
AESTHETICS/FORM	D	D	C	D
OVERALL CONDITION	**D**	**D**	**C**	**D**


TREE #173




TREE #174



TREE #175



TREE #176



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	177	178	179	180
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	14,13	20	15,15	12,11,6
HEIGHT (feet)	12	25	35	15
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	x
2 WEAK MAIN CROTCH(ES)				
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK	x	x	x	x
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE	x	x	x	x
12 SOIL BUILDUP @ BASE	x	x	x	x
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING			x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				
REMOVE	x	x	x	x
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	D	D	D	D
STRUCTURE	D	D	D	D
AESTHETICS/FORM	D	D	D	D
OVERALL CONDITION	**D**	**D**	**D**	**D**


TREE #177




TREE #178



TREE #179



TREE #180



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	181	182	183	184
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	5	19,13	6	14,8
HEIGHT (feet)	9	45	22	29
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				
2 WEAK MAIN CROTCH(ES)		x		x
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK			x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE	x		x	
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES		x	x	x
11 FIRE DAMAGE	x	x	x	x
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)		x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)	x			
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	D	C	D	D
STRUCTURE	C	C	D	C
AESTHETICS/FORM	C	C	D	C
OVERALL CONDITION	**C**	**C**	**D**	**C**


TREE #181




TREE #182



TREE #183



TREE #184



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 184 Large cavity in basal area

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	185	186	187	188
SPECIES: *(Quercus agrifolia)*				
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	6	14,13	18	12
HEIGHT (feet)	14	25	27	26
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				x
2 WEAK MAIN CROTCH(ES)			x	
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK		x	x	
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE		x	x	x
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES		x	x	
11 FIRE DAMAGE	x	x	x	x
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				
REMOVE			x	x
ENCROACHMENT INTO (TPZ)	x	x		
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)			x	x
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	D	D	D	D
STRUCTURE	D	C	D	D
AESTHETICS/FORM	D	C	D	D
OVERALL CONDITION	**D**	**C**	**D**	**D**


TREE #185




TREE #186



TREE #187



TREE #188



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 185 New growth is apearing after fire damage

TREE # 187 High probabiltiy of limb failure

TREE # 188 Extensive damage

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	189	190	191	192
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	24	14,13,13	24,14	19
HEIGHT (feet)	40	30	36	29
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING		x		x
2 WEAK MAIN CROTCH(ES)	x	x	x	
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK	x	x	x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK	x	x	x	x
7 THIN FOLIAGE	x	x		
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES	x	x	x	x
11 FIRE DAMAGE	x	x	x	x
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)		x		x
REMOVE	x			
ENCROACHMENT INTO (TPZ)			x	
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)	x	x	x	x
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	D	D	D	D
STRUCTURE	D	D	C	D
AESTHETICS/FORM	D	D	C	D
OVERALL CONDITION	**D**	**D**	**C**	**D**


TREE #189




TREE #190



TREE #191



TREE #192



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 189 Extensive fire damage, large basal cavity

TREE # 190 Extensive fire damage, large basal cavity

TREE # 191 Extensive fire damage, large basal cavity

TREE # 192 Cavity in base

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	193	194	195	196
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	15,9,11,10,12	13	18	12
HEIGHT (feet)	40	30	34	24
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING		x	x	x
2 WEAK MAIN CROTCH(ES)	x			
3 DEAD BRANCHES/TIP DECLINE	x			x
4 CAVITY/WOUND ON TRUNK	x		x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES	x			
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE		x	x	x
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x			
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)		x		
REMOVE				
ENCROACHMENT INTO (TPZ)	x		x	x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)	x			
RATING				
OVERALL HEALTH	C	B	B	B
STRUCTURE	C	B	C	C
AESTHETICS/FORM	C	B	C	C
OVERALL CONDITION	**C**	**B**	**C**	**C**


TREE #193




TREE #194



TREE #195



TREE #196



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 193 Cavity in trunk may contribute to trunk failures

TREE # 195 Due to the lean, tree prone to failure

TREE # 196 Due to the lean, tree prone to failure

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	197	198	199	200
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	14	21	14,10	7
HEIGHT (feet)	20	45	22	20
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x		x	
2 WEAK MAIN CROTCH(ES)	x	x	x	
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK	x	x	x	
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE			x	
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE			x	x
13 RE-GROWTH FROM STUMP	x	x		
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE	x	x		
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)			x	x
REMOVE				
ENCROACHMENT INTO (TPZ)	x	x		
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)	x	x		
MODERATE RISK (visible weak area)			x	
RATING				
OVERALL HEALTH	C	C	D	D
STRUCTURE	C	C	D	C
AESTHETICS/FORM	C	C	D	C
OVERALL CONDITION	**C**	**C**	**D**	**C**


TREE #197




TREE #198



TREE #199



TREE #200



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 197 Cavity with decay - may contribute to failure

TREE # 198 Poorly attach multi trunks, prone to failure

TREE # 199 Extensive fire damage

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	201	202	203	204
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	12,8	7,6,5	4	4,5
HEIGHT (feet)	24	20	11	15
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x			
2 WEAK MAIN CROTCH(ES)	x			
3 DEAD BRANCHES/TIP DECLINE	x	x		
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE		x		
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	B	C	B	B
STRUCTURE	B	B	B	C
AESTHETICS/FORM	B	B	C	C
OVERALL CONDITION	**B**	**B**	**C**	**C**


TREE #201




TREE #202



TREE #203



TREE #204



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	205	206	207	208
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	5,3	3,3,3	6,5,4	3
HEIGHT (feet)	11	12	18	10
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				
2 WEAK MAIN CROTCH(ES)	x			
3 DEAD BRANCHES/TIP DECLINE		x	x	
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP	x			
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	B
STRUCTURE	C	C	C	B
AESTHETICS/FORM	C	C	C	B
OVERALL CONDITION	**C**	**C**	**C**	**B**


TREE #205




TREE #206



TREE #207



TREE #208



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	209	210	211	212
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	3	4,4,3,2,2	3,4,3,3,2	3
HEIGHT (feet)	10	15	17	9
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				
2 WEAK MAIN CROTCH(ES)				
3 DEAD BRANCHES/TIP DECLINE				
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	B	B	B	B
STRUCTURE	B	B	B	B
AESTHETICS/FORM	B	B	B	B
OVERALL CONDITION	**B**	**B**	**B**	**B**


TREE #209




TREE #210



TREE #211



TREE #212



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	213	214	215	216
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	3	3,4,2	8	25
HEIGHT (feet)	11	11	19	42
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				x
2 WEAK MAIN CROTCH(ES)				x
3 DEAD BRANCHES/TIP DECLINE				x
4 CAVITY/WOUND ON TRUNK				x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				x
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				x
TREATMENT				
PRUNE BY CROWN CLEANING				x
PRUNE BY CROWN THINNING				x
PRUNE BY CROWN REDUCTION				x
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				x
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	B	B	B	B
STRUCTURE	C	C	B	C
AESTHETICS/FORM	C	C	B	C
OVERALL CONDITION	**C**	**C**	**B**	**C**


TREE #213




TREE #214



TREE #215



TREE #216



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 216 Weight reduction pruning and cabling for major limb structure and large cavity in trunk

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	217	218	219	220
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	33	5,3,4	28	14,9,8
HEIGHT (feet)	35	15	50	30
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				x
2 WEAK MAIN CROTCH(ES)	x			x
3 DEAD BRANCHES/TIP DECLINE			x	x
4 CAVITY/WOUND ON TRUNK	x		x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				x
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES	x			x
11 FIRE DAMAGE				x
12 SOIL BUILDUP @ BASE	x		x	x
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x			x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION	x			x
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE	x			
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				x
MODERATE RISK (visible weak area)	x			
RATING				
OVERALL HEALTH	B	B	C	D
STRUCTURE	C	B	B	D
AESTHETICS/FORM	C	B	B	D
OVERALL CONDITION	**C**	**B**	**B**	**D**


TREE #217




TREE #218



TREE #219



TREE #220



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 217 Needs cables

TREE # 219 Large cavity in trunk

TREE # 220 Risk of trunk failure

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	221	222	223	224
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	14,13	40	18,15	24
HEIGHT (feet)	28	40	38	42
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	
2 WEAK MAIN CROTCH(ES)	x	x	x	
3 DEAD BRANCHES/TIP DECLINE	x	x		
4 CAVITY/WOUND ON TRUNK	x	x	x	
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK		x		
7 THIN FOLIAGE	x	x		
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES		x		
11 FIRE DAMAGE	x	x		
12 SOIL BUILDUP @ BASE			x	
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x		x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION	x		x	x
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				x
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x			
REMOVE		x		
ENCROACHMENT INTO (TPZ)			x	x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)		x		
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)			x	x
RATING				
OVERALL HEALTH	D	D	C	D
STRUCTURE	C	D	C	C
AESTHETICS/FORM	C	D	C	C
OVERALL CONDITION	**C**	**D**	**C**	**C**


TREE #221




TREE #222



TREE #223



TREE #224



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 222 Trunk is hollow, center burned out - **remove immediately**

TREE # 224 Prune for weight reduction, Remove South trunk due to cavity.

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	225	226	227	228
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	28	48	22	20
HEIGHT (feet)	43	55	50	38
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING			x	
2 WEAK MAIN CROTCH(ES)	x	x	x	x
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK	x	x	x	x
5 HANGERS/BROKEN LIMB(S)	x			
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE	x	x	x	x
8 DROUGHT STRESSED	x			
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES		x	x	x
11 FIRE DAMAGE		x	x	x
12 SOIL BUILDUP @ BASE		x		
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING		x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				x
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE		x		
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)		x		x
REMOVE	x		x	
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)	x		x	
SEVERE RISK (visible weak area)		x		
MODERATE RISK (visible weak area)				x
RATING				
OVERALL HEALTH	D	D	D	D
STRUCTURE	D	C	D	B
AESTHETICS/FORM	D	C	D	B
OVERALL CONDITION	**D**	**C**	**D**	**C**


TREE #225




TREE #226



TREE #227



TREE #228



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 225 Large cavity in base of tree

TREE # 226 Cavity in base of tree, heavy end weight on branches

TREE # 227 Large cavities in trunk, loose bark from fire damage

TREE # 228 Cavity in base, loose bark from fire damage

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	229	230	231	232
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	22	19	14	27
HEIGHT (feet)	50	50	22	40
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	x
2 WEAK MAIN CROTCH(ES)	x	x	x	
3 DEAD BRANCHES/TIP DECLINE	x	x	x	
4 CAVITY/WOUND ON TRUNK	x		x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK	x			
7 THIN FOLIAGE	x			
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES	x	x	x	x
11 FIRE DAMAGE	x			
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION	x	x	x	x
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)		x	x	
REMOVE	x			
ENCROACHMENT INTO (TPZ)				x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)	x		x	
MODERATE RISK (visible weak area)		x		x
RATING				
OVERALL HEALTH	D	C	C	C
STRUCTURE	D	D	D	C
AESTHETICS/FORM	D	D	D	C
OVERALL CONDITION	**D**	**D**	**D**	**C**


TREE #229




TREE #230



TREE #231



TREE #232



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 229 Extreme fire damage, cavity in trunk

TREE # 232 Large cavity in the base

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	233	234	235	236
SPECIES: *(Quercus agrifolia)*				
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	11	30,16	35	28
HEIGHT (feet)	14	58	62	55
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING		x		
2 WEAK MAIN CROTCH(ES)		x	x	x
3 DEAD BRANCHES/TIP DECLINE		x	x	x
4 CAVITY/WOUND ON TRUNK		x	x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK		x		x
7 THIN FOLIAGE			x	x
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES			x	x
11 FIRE DAMAGE		x		
12 SOIL BUILDUP @ BASE		x		
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				
REMOVE	x	x	x	x
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)	x		x	x
SEVERE RISK (visible weak area)		x		
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	Dead	d	d	d
STRUCTURE		d	d	d
AESTHETICS/FORM		d	d	d
OVERALL CONDITION		**d**	**d**	**d**


TREE #233




TREE #234



TREE #235



TREE #236



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 233 This tree is dead and should be removed immediately

TREE # 234 Large cavity on tension side of the trunk- structures are target

TREE # 235 Large cavity in trunk, large dead stub in canopy, weak main crotch

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	237	238	239	240
SPECIES: *(Quercus agrifolia)*				
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	20	29,27	32	48
HEIGHT (feet)	50	60	45	60
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING		x	x	x
2 WEAK MAIN CROTCH(ES)		x	x	x
3 DEAD BRANCHES/TIP DECLINE		x	x	x
4 CAVITY/WOUND ON TRUNK		x	x	
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK		x		
7 THIN FOLIAGE		x		
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES		x	x	x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE			x	
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				
REMOVE	x		x	
ENCROACHMENT INTO (TPZ)		x		x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)	x			
SEVERE RISK (visible weak area)		x	x	
MODERATE RISK (visible weak area)				x
RATING				
OVERALL HEALTH	Dead	D	C	C
STRUCTURE		D	C	C
AESTHETICS/FORM		D	C	C
OVERALL CONDITION		**D**	**C**	**C**


TREE #237




TREE #238



TREE #239



TREE #240



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 237 This tree is dead and should be removed immediately

TREE # 238 After trimming and weight reduction, cable main trunks

TREE # 239 Cavity in trunk, weak main crotch, high target area

TREE # 240 Install cable in large limb growing south


Note: Regarding Tree #237, an area 1 1/2 times the height of the tree should be secured so no one can enter near the tree

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	241	242	243	244
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	16	14	14	29,26
HEIGHT (feet)	40	25	38	60
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	
2 WEAK MAIN CROTCH(ES)				x
3 DEAD BRANCHES/TIP DECLINE	x			x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE	x	x	x	x
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x			
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				x
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	B	B	B	B
STRUCTURE	C	C	B	B
AESTHETICS/FORM	C	C	B	B
OVERALL CONDITION	**C**	**C**	**B**	**B**


TREE #241




TREE #242



TREE #243



TREE #244



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 244 Install cables for tree main trunks

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	245	246	247	248
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	39	34	18	25
HEIGHT (feet)	38	55	30	30
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	x
2 WEAK MAIN CROTCH(ES)	x	x		
3 DEAD BRANCHES/TIP DECLINE				
4 CAVITY/WOUND ON TRUNK	x	x		
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES	x			
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE			x	x
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x			
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION	x	x		
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE	x	x		
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)	x	x		
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	B	B	B	B
STRUCTURE	C	C	B	B
AESTHETICS/FORM	B	C	B	B
OVERALL CONDITION	**B**	**C**	**B**	**B**


TREE #245




TREE #246



TREE #247



TREE #248



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 245 Large cavity at base of tree, cavities in limbs over street

TREE # 246 One should expect more failures in this tree, cabling may reduce failures

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	249	250	251	252
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	18	15	19,9	10,8,8,7
HEIGHT (feet)	28	40	55	
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	
2 WEAK MAIN CROTCH(ES)				x
3 DEAD BRANCHES/TIP DECLINE				x
4 CAVITY/WOUND ON TRUNK				x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE	x	x	x	x
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				x
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	B	C	B	C
STRUCTURE	B	C	C	C
AESTHETICS/FORM	B	C	C	C
OVERALL CONDITION	**B**	**C**	**C**	**C**


TREE #249




TREE #250



TREE #251



TREE #252



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	253	254	255	256
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	19	7	45	9
HEIGHT (feet)	38	17	65	19
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x		x
2 WEAK MAIN CROTCH(ES)			x	
3 DEAD BRANCHES/TIP DECLINE				
4 CAVITY/WOUND ON TRUNK	x	x		x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES			x	
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE	x	x	x	x
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION			x	
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)	x			
RATING				
OVERALL HEALTH	B	C	B	B
STRUCTURE	C	D	B	C
AESTHETICS/FORM	C	D	B	C
OVERALL CONDITION	**C**	**D**	**B**	**C**


TREE #253




TREE #254



TREE #255



TREE #256



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 255 I suggest weight reduction, trimming and cabling

TREE #

TREE #

TREE #


TREE #

TREE #


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	257	258	259	260
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	30	54	66	38
HEIGHT (feet)	65	70	60	50
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x		
2 WEAK MAIN CROTCH(ES)	x	x	x	x
3 DEAD BRANCHES/TIP DECLINE	x			x
4 CAVITY/WOUND ON TRUNK	x		x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES	x		x	x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE	x		x	
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION		x	x	x
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				x
CABLE OR BRACE		x	x	x
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)			x	
MODERATE RISK (visible weak area)	x	x		
RATING				
OVERALL HEALTH	C	B	B	B
STRUCTURE	B	B	C	C
AESTHETICS/FORM	B	B	C	C
OVERALL CONDITION	**B**	**B**	**C**	**C**


TREE #257




TREE #258



TREE #259



TREE #260



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 257 I recommend installing cable in trunk over roof and weight reduction

TREE # 258 I recommend several cables for this tree

TREE # 259 Large cavity in trunk and limbs, tree failure is probable without notice

TREE # 260 Install cables in main leaders, further inspection of the root flare is recommended after soil is removed, decay on trunk at grade, also water leak near root flare


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	261	262	263	264
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	27	32,24	21	21,21,17,19
HEIGHT (feet)	38	75	55	75
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	x
2 WEAK MAIN CROTCH(ES)	x	x		x
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK	x	x	x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE			x	
10 CAVITY/WOUND IN BRANCHES		x		x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE		x	x	x
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x		
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION		x		x
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x		x
REMOVE			x	
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)	x		x	x
MODERATE RISK (visible weak area)		x		
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE #261




TREE #262



TREE #263



TREE #264



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 261 Large cavity with decay, below soil grade

TREE # 262 Recommend weight reduction, trimming and cabling

TREE # 263 Over 50% of the trunk is dead above the root flare, remove the tree


TREE # 264 This tree has a large basal cavity, remove soil from root flare and perform a root and root flare assessment. Tree may need removal. The target area if the tree fails is houses and property.

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	265	266	267	268
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	22	34	22,20	30,20,19
HEIGHT (feet)	65	70	32	48
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	
2 WEAK MAIN CROTCH(ES)		x	x	
3 DEAD BRANCHES/TIP DECLINE		x	x	
4 CAVITY/WOUND ON TRUNK	x	x	x	
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE		x		
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES		x	x	
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE		x	x	
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				x
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x			
REMOVE			x	
ENCROACHMENT INTO (TPZ)		x		x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)			x	
SEVERE RISK (visible weak area)	x	x		
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	D	D	C	C
STRUCTURE	C	C	D	C
AESTHETICS/FORM	C	C	D	C
OVERALL CONDITION	**C**	**C**	**D**	**C**


TREE #265




TREE #266



TREE #267



TREE #268



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 265 I recommend weight reduction - tree leans over structure

TREE # 266 Based on what I could see, this tre needs further assessment & possible removal

TREE # 267 Over 50% of trunk is dead with cavities, I recommend tree be removed

TREE # 268 I recommend weight reduction and trimming

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	269	270	271	272
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	17	42	17,15	20
HEIGHT (feet)	40	60	40	65
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x		x	x
2 WEAK MAIN CROTCH(ES)		x	x	
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK		x	x	
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES		x		
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE		x	x	
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	D	C
STRUCTURE	C	C	D	C
AESTHETICS/FORM	C	C	D	C
OVERALL CONDITION	**C**	**C**	**D**	**C**


TREE #269




TREE #270



TREE #271



TREE #272



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 269 I recommend installing cables in this tree

TREE # 270 Leans to the south

TREE # 271 Leans to the south

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	273	274	275	276
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	24	35,27	22	14
HEIGHT (feet)	45	70	38	38
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
LEANING	x	x	x	
WEAK MAIN CROTCH(ES)	x	x		x
DEAD BRANCHES/TIP DECLINE	x	x		x
CAVITY/WOUND ON TRUNK	x			
HANGERS/BROKEN LIMB(S)		x		
MAINSTEM DIEBACK	x			
THIN FOLIAGE				
DROUGHT STRESSED				
DISEASED/INSECT DAMAGE	x			
0 CAVITY/WOUND IN BRANCHES		x		
FIRE DAMAGE				
SOIL BUILDUP @ BASE	x	x	x	x
3 RE-GROWTH FROM STUMP				
EXPOSED STRUCTURAL ROOTS				
DEAD BUTTRESS ROOTS				
5 VISIBLE GIRDLING ROOTS				
NUTRIENT IMBALANCE/OTHER				
CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE	x	x		
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				x
REMOVE	x			
ENCROACHMENT INTO (TPZ)		x	x	
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)	x			
MODERATE RISK (visible weak area)		x		
RATING				
OVERALL HEALTH	D	C	B	B
STRUCTURE	D	C	C	B
AESTHETICS/FORM	D	C	C	B
OVERALL CONDITION	**D**	**C**	**C**	**B**


TREE #273




TREE #274



TREE #275



TREE #276



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 273 I recommend this tree be removed - Oak root fungus on root flare

TREE # 274 I recommend cables be installed for main trunks

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	277	278	279	280
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	25	30,20	3	35,30
HEIGHT (feet)	55	70	12	80
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x		
2 WEAK MAIN CROTCH(ES)		x		x
3 DEAD BRANCHES/TIP DECLINE				x
4 CAVITY/WOUND ON TRUNK		x		
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x		x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				x
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x		x
REMOVE				
ENCROACHMENT INTO (TPZ)			x	
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	B	B	B	B
STRUCTURE	B	C	C	B
AESTHETICS/FORM	B	C	C	B
OVERALL CONDITION	**B**	**C**	**C**	**B**


TREE #277




TREE #278



TREE #279



TREE #280



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	281	282	283	284
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	29,15	32,34	19,18	22,19,18,13
HEIGHT (feet)	70	70	60	55
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x			x
2 WEAK MAIN CROTCH(ES)	x	x	x	x
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK		x	x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				x
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				x
10 CAVITY/WOUND IN BRANCHES	x	x		x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				x
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				x
CABLE OR BRACE				x
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				x
RATING				
OVERALL HEALTH	B	B	B	D
STRUCTURE	B	B	B	C
AESTHETICS/FORM	B	B	B	C
OVERALL CONDITION	**B**	**B**	**B**	**C**


TREE #281




TREE #282



TREE #283



TREE #284



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 284 Fungus fruiting bodies on the trunk;

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	285	286	287	288
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	8,6,5,6	3,2,2	19,18	38
HEIGHT (feet)	24	14	50	60
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				
2 WEAK MAIN CROTCH(ES)	x		x	x
3 DEAD BRANCHES/TIP DECLINE	x		x	x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES			x	
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE	x			
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				x
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				x
REMOVE				
ENCROACHMENT INTO (TPZ)	x	x	x	
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	B	B	B	B
STRUCTURE	B	B	B	B
AESTHETICS/FORM	B	B	B	B
OVERALL CONDITION	**B**	**B**	**B**	**B**


TREE #285




TREE #286



TREE #287



TREE #288



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 288 Crown reduction to reduce end weight on horizontal branches

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	289	290	291	292
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	36,34	20	multi	38
HEIGHT (feet)	58	40	65	45
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	
2 WEAK MAIN CROTCH(ES)	x		x	
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK	x		x	
5 HANGERS/BROKEN LIMB(S)	x			
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE			x	
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES			x	
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE	x	x		
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	
PRUNE BY CROWN THINNING			x	
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE			x	
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)			x	
MODERATE RISK (visible weak area)	x			
RATING				
OVERALL HEALTH	C	B	D	B
STRUCTURE	B	C	C	B
AESTHETICS/FORM	B	C	C	B
OVERALL CONDITION	**B**	**C**	**C**	**B**


TREE #289




TREE #290



TREE #291



TREE #292



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 289 Large wound on trunk

TREE # 290 Trimming and cabling is need promptly

TREE # 291 Trunk Diameter (in inches) 21,20,19,14,20

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	293	294	295	296
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	10	7	9,8	18
HEIGHT (feet)	28	21	32	50
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				x
2 WEAK MAIN CROTCH(ES)			x	
3 DEAD BRANCHES/TIP DECLINE	x		x	x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	B	B	B	B
STRUCTURE	C	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE #293




TREE #294



TREE #295



TREE #296



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	297	298	299	300
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	9,9,7,6,8	7,6,6,6,6	4	7,6
HEIGHT (feet)	30	20	12	20
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING		x		x
2 WEAK MAIN CROTCH(ES)	x			
3 DEAD BRANCHES/TIP DECLINE	x	x	x	
4 CAVITY/WOUND ON TRUNK				x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE	x	x		
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	B	C	C	C
STRUCTURE	B	C	C	C
AESTHETICS/FORM	B	C	C	C
OVERALL CONDITION	**B**	**C**	**C**	**C**


TREE #297




TREE #298



TREE #299



TREE #300



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #


TREE #

TREE #


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	301	302	303	304
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	16,16	18	28	12
HEIGHT (feet)	38	30	60	35
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				
2 WEAK MAIN CROTCH(ES)	x	x	x	
3 DEAD BRANCHES/TIP DECLINE	x	x	x	
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	B	C
STRUCTURE	C	C	B	C
AESTHETICS/FORM	C	C	B	C
OVERALL CONDITION	**C**	**C**	**B**	**C**


TREE #301




TREE #302



TREE #303



TREE #304



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	305	306	307	308
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	4	17	7	8,7
HEIGHT (feet)	12	40	27	22
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				
2 WEAK MAIN CROTCH(ES)		x		
3 DEAD BRANCHES/TIP DECLINE		x		x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE		x		
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	B	C	C	C
STRUCTURE	C	C	D	C
AESTHETICS/FORM	C	C	D	C
OVERALL CONDITION	**C**	**C**	**D**	**C**


TREE #305




TREE #306



TREE #307



TREE #308



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 306 I recommend a cable for main trunks

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	309	310	311	312
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	14	8	10	9
HEIGHT (feet)	35	38	39	25
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x		x
2 WEAK MAIN CROTCH(ES)	x			
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				
REMOVE				
ENCROACHMENT INTO (TPZ)	x	x	x	x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE #309




TREE #310



TREE #311



TREE #312



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	313	314	315	316
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	18	5,4	5	10
HEIGHT (feet)	40	22	26	34
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				
2 WEAK MAIN CROTCH(ES)				x
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)				
REMOVE				
ENCROACHMENT INTO (TPZ)	x	x	x	x
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	D	C
AESTHETICS/FORM	C	C	D	C
OVERALL CONDITION	**C**	**C**	**D**	**C**


TREE #313




TREE #314



TREE #315



TREE #316



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	317	318	319	320
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	8	7,7	7,3	8
HEIGHT (feet)	30	32	22	26
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING				
2 WEAK MAIN CROTCH(ES)	x	x	x	
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK				
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING				
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION				
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)		x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)	x			
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	D	C	C	C
AESTHETICS/FORM	D	C	C	C
OVERALL CONDITION	**D**	**C**	**C**	**C**


TREE #317




TREE #318



TREE #319



TREE #320



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE #

TREE #

TREE #

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	321	322	323	324
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	8,7	5	32,32,19	38
HEIGHT (feet)	26	20	70	65
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING			x	
2 WEAK MAIN CROTCH(ES)	x		x	x
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK			x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				x
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES				x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE			x	x
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING			x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION			x	x
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE			x	
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)	x	x	x	
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	B	B
AESTHETICS/FORM	C	C	B	B
OVERALL CONDITION	**C**	**C**	**B**	**B**


TREE #321




TREE #322



TREE #323



TREE #324



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 323 I recommend the installation of several EHS cables 1/2" dia. with 5/8" diameter eyebolts

TREE #

TREE # 324 Cabling same as recommend for Tree #323 and also there is a large cavity in the main trunk

TREE #

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	325	326	327	328
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	20	33	63	18,15
HEIGHT (feet)	46	38	52	48
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	
2 WEAK MAIN CROTCH(ES)		x	x	x
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK	x		x	
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE			x	
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES			x	
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x		x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION	x		x	x
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE			x	x
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)		x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)	x			
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)			x	
MODERATE RISK (visible weak area)	x			
RATING				
OVERALL HEALTH	c	b	c	c
STRUCTURE	c	b	d	c
AESTHETICS/FORM	c	b	d	c
OVERALL CONDITION	**c**	b	**d**	**c**


TREE #325




TREE # 326



TREE # 327



TREE # 328



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 325

TREE # 326

TREE # 327 Large cavity in base of tree, needs weight reduction pruning and annual assessment

TREE # 328

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	329	330	331	332
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	30,29	26,24,23	37	34
HEIGHT (feet)	55	48	60	38
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	x
2 WEAK MAIN CROTCH(ES)	x	x	x	x
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK	x	x	x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				x
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES	x	x	x	x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED	x			
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION	x		x	
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE	x			
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)			x	x
SEVERE RISK (visible weak area)	x	x		
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	c	c	c	c
STRUCTURE	d	c	c	d
AESTHETICS/FORM	c	c	c	d
OVERALL CONDITION	**c**	**c**	**c**	**d**


TREE # 329




TREE # 330



TREE # 331



TREE # 332



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 329 Large cavity in the base needs cables and weight reduction trimming

TREE # 330 Large cavity in the base, needs weight reduction trimming.

TREE # 331 Needs prompt attention by your tree service possibly removal.

TREE # 332 Large basal cavity approximately 30% of trunk is dead, may need removal

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	333	334	335	336
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	35	36,20,17,23	32,28	24,19
HEIGHT (feet)	42	55	50	40
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	x
2 WEAK MAIN CROTCH(ES)	x	x	x	x
3 DEAD BRANCHES/TIP DECLINE				x
4 CAVITY/WOUND ON TRUNK			x	x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES	x		x	x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING		x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION		x	x	x
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE	x		x	x
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)		x	x	x
MODERATE RISK (visible weak area)	x			
RATING				
OVERALL HEALTH	b	b	c	c
STRUCTURE	b	b	c	d
AESTHETICS/FORM	b	b	c	d
OVERALL CONDITION	**b**	**b**	**c**	**d**


TREE #333




TREE #334



TREE #335



TREE # 336



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 333

TREE # 334 Needs weight reduction, thinning and cabling

TREE # 335 Needs attention one should expect major limb failure

TREE # 336 Needs weight reduction trimming possibly removal

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	337	338	339	340
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	70	30	23	19,12,11,8
HEIGHT (feet)	60	52	35	40
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	x
2 WEAK MAIN CROTCH(ES)	x	x	x	x
3 DEAD BRANCHES/TIP DECLINE		x	x	x
4 CAVITY/WOUND ON TRUNK	x	x		x
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES	x	x	x	x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION	x	x	x	
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE		x	x	
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)	x			
MODERATE RISK (visible weak area)		x	x	x
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE # 337




TREE # 338



TREE # 339



TREE # 340



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 337 Needs cabling and crown cleaning

TREE # 338 Large cavity in the base, needs weight reduction trimming.

TREE # 339 Needs prompt attention by your tree service possibly removal.

TREE # 340

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	341	342	343	344
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	39	25	25,29,13	22,17,14
HEIGHT (feet)	65	38	50	50
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING		x	x	x
2 WEAK MAIN CROTCH(ES)	x	x	x	x
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK	x	x	x	x
5 HANGERS/BROKEN LIMB(S)				x
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE		x		
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES	x	x	x	x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x		x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION	x		x	x
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)		x		
SEVERE RISK (visible weak area)	x		x	x
MODERATE RISK (visible weak area)				
RATING				
OVERALL HEALTH	c	c	c	c
STRUCTURE	c	d	c	c
AESTHETICS/FORM	c	d	c	c
OVERALL CONDITION	**c**	**d**	**c**	**c**


TREE # 341




TREE # 342



TREE # 343



TREE #344



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 341 Needs weight reduction and crown cleaning

TREE # 342 I recommend tree #342 be removed

TREE # 343 Needs weight reduction trimming

TREE # 344 Leans over parking area needs trimming and cabling

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	345	346	347	348
SPECIES: *(Quercus agrifolia)*	x	x	x	x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	18,15,14,8	24,19,15	20,19	22,20,24
HEIGHT (feet)	50	60	35	65
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x	x	x
2 WEAK MAIN CROTCH(ES)	x	x	x	x
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK		x	x	x
5 HANGERS/BROKEN LIMB(S)		x		x
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE		x		
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES		x		x
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x	x	x
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION	x	x	x	x
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE				
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x	x	x
REMOVE				
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)		x	x	x
MODERATE RISK (visible weak area)	x			
RATING				
OVERALL HEALTH	C	C	C	C
STRUCTURE	C	C	C	C
AESTHETICS/FORM	C	C	C	C
OVERALL CONDITION	**C**	**C**	**C**	**C**


TREE # 345




TREE # 346



TREE # 347



TREE # 348



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 345 Needs weight reduction and crown cleaning

TREE # 346 Needs trimming and cabling

TREE # 347 Needs weight reduction trimming

TREE # 348 Needs weight reduction trimming trimming and crown cleaning

TREE #


TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)


SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	349	350	351	352
SPECIES: *(Quercus agrifolia)*	x	x		x
SPECIES: *(Quercus lobata)*				
TRUNK DIAMETER (inches)	58	32	Multi	6,4,3,3,2
HEIGHT (feet)	55	28	15	15
SPREAD (feet) N/S/E/W				
PHYSICAL CONDITION				
1 LEANING	x	x		
2 WEAK MAIN CROTCH(ES)	x	x		
3 DEAD BRANCHES/TIP DECLINE	x	x	x	x
4 CAVITY/WOUND ON TRUNK	x	x		
5 HANGERS/BROKEN LIMB(S)				
6 MAINSTEM DIEBACK				
7 THIN FOLIAGE				
8 DROUGHT STRESSED				
9 DISEASED/INSECT DAMAGE				
10 CAVITY/WOUND IN BRANCHES	x	x		
11 FIRE DAMAGE				
12 SOIL BUILDUP @ BASE				
13 RE-GROWTH FROM STUMP				
14 EXPOSED STRUCTURAL ROOTS				
15 DEAD BUTTRESS ROOTS				
16 VISIBLE GIRDLING ROOTS				
17 NUTRIENT IMBALANCE/OTHER				
18 CABLED OR BRACED				
TREATMENT				
PRUNE BY CROWN CLEANING	x	x		
PRUNE BY CROWN THINNING				
PRUNE BY CROWN REDUCTION	x	x		
TREAT FOR INSECTS/DISEASE				
REMOVE SOIL BUILDUP				
CABLE OR BRACE		x		
APPLY NUTRIENTS/MULCH				
OBSERVATIONS				
NO ENCROAHMENT (TPZ)	x	x		
REMOVE			x	x
ENCROACHMENT INTO (TPZ)				
TRANSPLANT ONSITE				
NOT TRANSPLANTABLE				
CRITICAL RISK (visible weak area)				
SEVERE RISK (visible weak area)				
MODERATE RISK (visible weak area)	x	x		
RATING				
OVERALL HEALTH	b	c	c	c
STRUCTURE	b	c	c	c
AESTHETICS/FORM	b	c	c	c
OVERALL CONDITION	**b**	**c**	**c**	**c**


TREE #349




TREE #350



TREE #351



TREE #352



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 349 Needs weight reduction and crown cleaning

TREE # 350 Leans over parking area, cavity in the base, needs attention from your tree service

TREE # 351 Scrub Oak (*Quercus berberidfolia*) Multi 6 trunks 2",3,3 total 18 inch diameter

TREE # 352


TREE #

TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)

SUMMARY OF VISUAL FIELD INSPECTION (OAK TREES)

TREE NUMBER	353				TREE # 353
SPECIES: *(Quercus agrifolia)*	x				
SPECIES: *(Quercus lobata)*					
TRUNK DIAMETER (inches)	Multi				
HEIGHT (feet)	40				
SPREAD (feet) N/S/E/W					
PHYSICAL CONDITION					
1 LEANING	x				
2 WEAK MAIN CROTCH(ES)	x				
3 DEAD BRANCHES/TIP DECLINE	x				
4 CAVITY/WOUND ON TRUNK	x				
5 HANGERS/BROKEN LIMB(S)					TREE #
6 MAINSTEM DIEBACK					
7 THIN FOLIAGE					
8 DROUGHT STRESSED					
9 DISEASED/INSECT DAMAGE					
10 CAVITY/WOUND IN BRANCHES	x				
11 FIRE DAMAGE					
12 SOIL BUILDUP @ BASE					
13 RE-GROWTH FROM STUMP					
14 EXPOSED STRUCTURAL ROOTS					
15 DEAD BUTTRESS ROOTS					
16 VISIBLE GIRDLING ROOTS					TREE #
17 NUTRIENT IMBALANCE/OTHER					
18 CABLED OR BRACED					
TREATMENT					
PRUNE BY CROWN CLEANING	x				
PRUNE BY CROWN THINNING					
PRUNE BY CROWN REDUCTION					
TREAT FOR INSECTS/DISEASE					
REMOVE SOIL BUILDUP					
CABLE OR BRACE					
APPLY NUTRIENTS/MULCH					
OBSERVATIONS					TREE #
NO ENCROAHMENT (TPZ)	x				
REMOVE					
ENCROACHMENT INTO (TPZ)					
TRANSPLANT ONSITE					
NOT TRANSPLANTABLE					
CRITICAL RISK (visible weak area)					
SEVERE RISK (visible weak area)					
MODERATE RISK (visible weak area)	x				
RATING					
OVERALL HEALTH	C				
STRUCTURE	C				
AESTHETICS/FORM	C				
OVERALL CONDITION	**C**				



(TPZ) TREE PROTECTION ZONE A=EXCELLENT B=GOOD C=FAIR D=POOR E=DECLINING F=DEAD

SPECIES/COMMENTS

TREE # 353 Large basal cavity with decay. If people are to be under the canopy of
TREE # this tree it would be rated a severe risk.
TREE # Multi trunk 20" 10" 12" 8" 5" 4" 3" diameters
TREE #
TREE #
TREE #

Prepared by Robert Hansen (Registered Consulting Arborist)

SECTION 4

RECOMMENDATIONS FOR OAK TREES LOCATED OVER HIGH-FREQUENCY USE AREAS (Pre-Existing Conditions-Unrelated to Proposed Construction)

There are Oak trees near frequent human-use areas, not impacted by the proposed development, but with risk conditions we believe could be improved by treatments such as crown reduction pruning, support cabling, or that should be removed altogether.

Arborists cannot detect every condition that could possibly lead to the structural failure or death of a tree. Trees are living organisms, subject to the destructive forces of nature, which sometimes fail in ways we do not fully understand. Conditions are often hidden within trees or below ground. Arborists cannot guarantee a tree's health or safety. Further, arborists cannot guarantee the effectiveness of remedial treatments, such as pruning or support cabling.

The following recommended measures are intended to reduce the risk of living near these trees. This work is recommended immediately. The owners of the trees, or the governing agency, may choose to accept or disregard the recommendations of the arborists, or seek additional advice.

Coast Live Oak, *Quercus agrifolia*
#216 Crown reduction pruning and crown cleaning.
#217 Crown reduction pruning and crown cleaning.

#220 Crown reduction pruning, crown cleaning.
#221 Crown reduction pruning and crown cleaning.
#222 Remove tree immediately due to hollow trunk.
#223 Crown reduction pruning and crown cleaning.
#224 Remove south trunk due to cavity. Crown reduction pruning and crown cleaning.

#225 Remove due to large basal cavity.
#226 Crown reduction pruning (20% of entire crown).
#227 Remove due to large trunk cavities.
#228 Crown reduction pruning, crown cleaning.
#229 Crown reduction pruning, crown cleaning.

#230 Crown reduction pruning, crown cleaning.
#231 Crown reduction pruning, crown cleaning.
#232 Crown reduction pruning, crown cleaning.
#233 Dead, remove immediately.
#234 Crown reduction pruning, crown cleaning.

#235 Remove tree due to trunk cavities.
#236 Remove tree due to basal and trunk cavities with decay, trunk oozing.
#237 This tree is dead and should be removed.
#238 Remove tree due to a large basal cavity, lean, branch cavities and dead wood.

#239 Crown reduction pruning, crown cleaning.
#241 Crown reduction pruning, crown cleaning.
#244 Crown reduction pruning, crown cleaning.

#245 Crown reduction pruning due to basal cavities and lean. (Placerita Canyon Rd)
#246 Crown reduction pruning (20% of whole size) due to poor attachments, large trunk and basal cavities. (Placerita Canyon Rd)

#253 Crown reduction on branches with cavities or over human use areas.
#255 Crown reduction (major) on south trunk over structure.
#257 Install two support cables (X pattern)

#258 Crown reduction over walks and street. (on Placerita Canyon Rd)
#259 Crown reduction pruning (major) due to cavities and poor attachments.
#260 Crown reduction over walks and street due to basal cavities and dead areas.
#261 Crown reduction pruning (major) due to basal cavity.
#262 Crown reduction pruning, crown cleaning.

#143 Crown reduction pruning, crown cleaning.

#262 Crown reduction pruning, crown cleaning.
#263 Drain water from base of trunk in rains.
#264 Further investigation/root crown excavation by a qualified Certified Arborist. Check for Armillaria mellea. If no root disease found, then crown reduction pruning and support cables.

#122 Crown reduction pruning, crown cleaning. Add one support cable.
#123 Crown reduction pruning.

#265 Major crown reduction pruning over building.
#266 Major crown reduction pruning, install three support cables.
#267 Remove tree due to basal cavity.
#268 Crown reduction and crown cleaning over walks and buildings. Install five support cables, all major trunks.

#323 Crown reduction pruning, crown cleaning.

#324 Crown reduction pruning, crown cleaning. Remove soil to trunk flare. Root crown excavation by a qualified Certified Arborist. Crown reduction pruning and support cables all major trunks.
#325 Crown reduction pruning, crown cleaning.

#102 Crown reduction pruning, crown cleaning.
#107 Crown reduction pruning, crown cleaning.
#108 Crown reduction pruning, crown cleaning.
#109 Crown reduction pruning, crown cleaning.
#110 Crown reduction pruning, crown cleaning.

#269 Crown clean. Install one cable. Direct irrigation away from tree trunk (ten feet minimum).
#271 Crown clean. Install three cable. Direct irrigation away from tree trunk (ten feet minimum).
#272 Crown clean. Install three cable. Direct irrigation away from tree trunk (ten feet minimum).
#273 Crown reduction and crown cleaning. Keep irrigation ten feet away from trunk.
#274 Crown reduction and crown cleaning. Install three support cables. Keep irrigation ten feet away from trunk.

North Campus
#327 Major crown reduction pruning over building. Property line/commonly owned tree needs permission of all owners prior to performance of any work. Base of tree needs further inspection.
#328 Crown clean, install one cable to low trunk.
#329 Crown reduction pruning, crown cleaning. Install two cables (X pattern).

#330 Crown reduction pruning, crown cleaning. Major weight reduction on 6, 8, and 10 inches diameter limbs. Install four to five support cables.
#331 Crown reduction pruning, crown cleaning.
#332 Crown reduction pruning, crown cleaning.

#333 Crown clean, install cables to support main leaders.
#334 Install cables to support main leaders, install two threaded rods.
#335 Remove low limb to east. Remove central limb due to decay. Install cables to support main leaders.
#336 Major crown reduction (remove limbs 4 to 8 inches diameter). Install cables to support main leaders.

#337 Crown reduction pruning, crown cleaning. Remove limb with cavity.

#338 Crown reduction.
#339 Crown reduction.
#340 Crown reduction pruning, crown cleaning. Install cables to main branches.

#341 Crown reduction and crown cleaning due to spread over adjacent building and patio. Install cables to main branches.

#342 Remove this Oak due to large basal cavity and advance trunk decay. Located in a patio near the parking lot.

#343 Major crown reduction, crown cleaning. Install cables to all main branches.
#344 Major crown reduction, crown cleaning. Install cables to all main branches.
#345 Major crown reduction, crown cleaning. Install cables to all main branches.
#346 Major crown reduction, crown cleaning. Install cables to all main branches.
#347 Major crown reduction, crown cleaning. Install cables to all main branches.

#348 Crown reduction and crown cleaning due to lean, cavities, and branch tip decline over parking area. Cable all main leaders.

#349 Crown reduction and crown cleaning due to spread over parking area. Cable all main leaders.

#350 Crown reduction and crown cleaning due to basal cavity and lean over parking area. Install cables and bracing. Install two, four inches diameter, steel pipe fabricated supports, set in concrete footings.

Note: Tree care contractor to inspect tree for structure before climbing.
Specifications for cabling hardware:
Support cables 3/8 inch or larger, extra strength, high-tension cable.
Eye bolts, drop forged 5/8 inch or larger.
These cabling recommendations are subject to cable installation contractor upgrade.

Section 5

RECOMMENDATIONS TO REDUCE IMPACT ON OAK TREES DURING CONSTRUCTION

Prevention of negative impacts is the key to oak tree preservation on construction sites. Chain link protection fencing, hand grading within tree protection zones (TPZ) with hand tools only, careful root pruning with hand tools as necessary, and on site supervision by the Oak Tree Consultant are methods that can help to successfully preserve oak trees. Roots larger than one inch diameter are to be preserved whenever possible.

Absorbing root damage is commonly caused by soil compaction by persons or vehicles, trenching, and changes in grade that inhibit oxygen exchange or remove roots. Except for City-approved encroachments, these activities should be avoided within tree protection zones.

1. Protective fencing will be needed and must be installed for the protection of all oak trees as needed. Install a fence a minimum of five feet in height and five feet beyond the end of the branches (dripline). Stakes shall be strong enough to secure the fence for the duration of the project.

   The fence is to remain in place at all times. A gate is necessary for tree maintenance personnel. No building materials or equipment are to be stored within the fenced area. No temporary buildings are permitted within the tree protection zone.

2. If the governing agency allows trenching within a tree protection zone, the project arborist must be present and properly directing trenching work to reduce impacts to the tree. Trenching must be performed with hand tools or The Air Spade.

   When installing utility lines (gas, water, landscape irrigation, etc.), if trenching is to occur within the protection zone of any tree, the project arborist must be present to help protect the interest of the trees.

3. The project consulting arborist shall be present during all grading operations within tree protection zones (TPZ). The tree protection zone is defined as the end of the branches (dripline) plus five feet. Hand grading, with hand tools only, is required within the TPZ.

4. Any root pruning, if necessary, shall be performed under the direction of the project's consulting arborist.

5. Disposing of waste such as cement, concrete, petroleum products, paint or any other material that may be toxic to plants shall not be permitted on site.

6. If questions arise regarding any action that may have negative impact on an oak tree, the project arborist shall be contacted and consulted with before any such action occurs. Damaging actions must be prevented, as little can be done after the damage occurs.

7. No equipment is to be used within the tree protection zone. Any digging, excavation, grading, or trenching within the tree protected zone should be done by hand in the presence of the project Oak Tree Consultant.

8. Any all work within Tree Protection Zones must be monitored by the Oak Tree Consultant as required by the governing agency.

Section 6

GENERAL RECOMMENDATIONS FOR OAK TREE MAINTENANCE

Implementing and maintaining favorable cultural conditions around Oak trees is the key to tree health. Disease and insect problems are much less likely to occur when trees are healthy. Soil and root zone treatments to improve growing conditions, such as adding mulch to the surface, soil aeration, watering during dry winter and spring seasons, and soil-analyzed nutrient application (fertilization) may be beneficial for tree health and longevity.

1. Pruning oak trees is generally limited to the removal of dead, diseased or poorly attached branches that may be a severe risk to humans or property. Pruning should be done under the direction of a qualified arborist.

2. Refrain from watering oak trees except in years of below average rainfall. Refrain from watering oaks from July until November and from applying water within three feet of the root flare.

3. Mulching the surface of the soil approximately three to four inches deep with oak leaves under the canopy of the tree is beneficial. Keep mulch back from the trunk of established trees approximately 12-18 inches.

4. Fertilizing oak trees may be necessary in some soils and site conditions. Have the soil analyzed before fertilization so that the necessary elements can be applied to the root zone.

5. Newly installed trees will need supplemental water for the first two years, especially in the root ball area. Cultivate the soil beyond the root ball for a distance of three feet and 18 inches deep to improve the area for root growth. Apply three to four inches of oak leaf mulch over the area of the root ball and cultivated area. Keep mulch back from the trunk by 12 inches.

6. Root system aeration, known as vertical mulching or radial trench mulching man be beneficial in certain circumstances. Composted organic matter, mycorrhizal fungi, gypsum, and soil penetrants may improve root growth.

7. Keep turf-grass away from established trees during landscaping (minimum distances at the direction of the consulting arborist). Competitive plantings should be avoided.

Any questions regarding this report should be directed to the oak tree consultants at (310) 926-1427 for Mr. Hansen or (818) 636-4917 for Craig Crotty.

Bob Hansen, ASCA

Craig Crotty, ASCA Member

ATTACHMENTS

- Assumptions and Limiting Conditions
- Curriculum Vitae (2)
- Tree Plan (seven sheets)

Assumptions and Limiting Conditions

The Consulting Arborist has no past, present or future interest in this property or the subject trees. Opinions contained herein are the independent and objective judgement of the Consultant relating to circumstances and observations made on the subject site.

The Consulting Arborist shall not be required to give testimony, perform site monitoring, provide further documentation, be deposed, or to attend any meeting, court or hearing, without subsequent contractual arrangements for this additional employment, including payment of additional fees for such services as described by the Consultant.

The recommendations contained in this report are the opinions of the Consulting Arborist at the time of inspection. These opinions are based on the knowledge, experience, and education of the Consultant. The field inspection was a visual, grade level tree assessment.

The owner of tree may choose to accept or disregard the recommendations of the Consultant, or seek additional advice to determine if a tree meets the owner's risk abatement standards.

No warranty is made, expressed or implied, that problems or deficiencies of the trees or the property will not occur in the future, from any cause. The Consultant shall not be responsible for damages or injuries caused by any tree defects and assumes no responsibility for the correction of defects or tree related problems.

It is assumed that statements of fact regarding property ownership, property boundaries, exact tree and structure locations are "as represented" by the client, in all verbal, written or drawn communications. The Consultant assumes no responsibility for verification of ownership or locations of property lines, or for results of any actions or recommendations based on inaccurate information.

It is assumed that any property referred to in this report is not in violation of any applicable codes, ordinances, statutes, or other governmental regulations.

This report may not be reproduced without the express permission of the Consulting Arborist and the client to whom the report was issued. Any change or alteration to this report invalidates the entire report.

Levels of risk are in three categories, Risk, Severe Risk, and Critical Risk. Any critical risk tree should be removed immediately. Some severe risk trees warrant immediate removal, refer to the field data forms. Risk trees may sometimes, with less frequency, be recommended for removal.

Client/Applicant _____ Date_____

Gilbert R. Hansen

Registered Consulting Arborist
7023 Semrad Road
West Hills, California 91307
818-703-8024
December 15, 2003

PROFESSIONAL EXPERIENCE

1973 – Present	Independent Consulting Arborist. Owner and operator of Bob Hansen Tree Preservation.
1963 to 1973	Independent Consulting Arborist. Owner and operator of Bay Cities Tree Preservation
1962 to 1963	Foreman – Humphrey Tree Service
1959 to 1962	Working Foreman, Job Estimator – Johnson and Thiermann Tree Preservation
1958 to 1959	Tree Service – Independent

AFFILIATIONS AND MEMBERSHIPS

Owner	Bob Hansen Tree Preservation
Gilbert R. Hansen	State Contractors License #649218
Member	American Society of Consulting Arborists
Member	California Oak Foundation
Member	Life Member International Society of Arboriculture 10201
Member	Western Chapter International Society of Arboriculture

EDUCATION AND LICENSES

California State Licensed Contractor 649218 C61/D49
Certified Arborist - International Society of Arboriculture Western Chapter #1142
American Society of Consulting Arborists
Registered Consulting Arborist Membership #352
Pierce College – Ornamental Pest Control and Tree Care
Tree Biology Workshop – Dr. Alex Shigo
Preserving Mature Trees during Construction seminars sponsored by the International Society of Arboriculture.
Advanced Hazard Tree Evaluation Workshop and Tree Preservation Workshop – Co-sponsored by the Utah Community Forest Council and International Society of Arboriculture – Rocky Mountain Chapter

CRAIG CROTTY
ARBOR CULTURE

Employment History: May 2001-Present, Owner, **Craig Crotty-Arbor Culture,** Glendale, CA. Consulting Arborist Services including: Diagnosis and Recommendations for Tree and Landscape Problems, Tree Preservation Plans and Monitoring for Conservation During Construction, Tree and Landscape Appraisal, Tree Risk Assessment, Tree Care and Management Specifications, Expert Witness Services, Insect and Disease Identification, Tree Inventories

Nov.1990-April 2001. Steven's Tree Experts, a Division of Landscape Engineering Inc., Pasadena, CA. Certified Arborist, Sales Representative and Project Coordinator.

June 1981-Aug. 1986. Landscape Design, Inc.San Francisco, CA. Landscape design/ builder.1973-1980. Construction Supervisor various locations throughout the San Francisco Bay Area, California.

Education: American Society of Consulting Arborists, Consulting Academy 2002

1989 B.A. Industrial Arts, Cum Laude
San Francisco State University.
Senior Research and Development Project:
Expandable Concrete Tree Well Cover.

1986-1989 Landscape Architecture Certification Program, University of California, Berkeley Extension.

Certification: Certified Arborist WC #749
International Society of Arboriculture

Contractor's License: California State License # 734117 (Past/No Longer Contracting)
C27 Landscape, C61/D49 Tree Care

Professional Societies: American Society of Consulting Arborists, Member
International Society of Arboriculture
Western Chapter, International Society of Arboriculture

P.O. Box 246, Verdugo City, CA 91046 Tel. 818 957-8824 Fax 818 957-8834
Email: oakdocuments@netzero.net **CV Date: October 3, 2005**

OAK TREE REPORT

VOLUME 2

Project Location:
The Masters's College
21726 Placerita Canyon Road
Santa Clarita, Ca 91321

Prepared for:
Mr. Robert L. Hatton
The Masters' College
21726 Placerita Canyon Road
Santa Clarita, Ca 91321

And
Mr. Gordon Jenewein
Development Planning Services
651 Via Alondra, Suite 711
Camarillo, Ca 93012
Tel 805 484-8303

October 3, 2005

Report Submitted By:
ROBERT HANSEN, ASCA
REGISTERED CONSULTING ARBORIST #352

7023 Semrad Road
West Hills, Ca 91307
818 703-8024

And
CRAIG CROTTY
ARBOR CULTURE
ASCA, Member

P.O Box 246
Verdugo City, Ca 91046
Direct 818 636-4917
Office 818 957-8824

CONTENTS

Volume II

Contents:

- Field Data Sheets — Section 1
- Appraisals — Section 2
- Copies of Photographs — Section 3

SECTION 1

TERMS EXPLAINED

1. **Following the tree # H.T stands for *Heritage Tree*:**
2. **Diameter at Breast Height *DBH* or @ 4.5 feet above grade:**
3. **Work believed to be beyond the Tree Protection Zone *No Impact*:**
4. **Wk Within 5ft. Zone work believed to be within 5 Feet beyond the drip-line:**
5. **WK Within Dripline from end of branch to the trunk:**

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
1	Quercus agrifolia	18"9"	x				
2	Quercus agrifolia	17"11"17"12"	x				
3 H.T	Quercus agrifolia	72"		x			Grading and retaining wall
4	Quercus agrifolia	4"	x				
5	Quercus agrifolia	11"9"			x		Grading
6	Quercus agrifolia	16"				x	Grading
7	Quercus agrifolia	9"				x	Grading
8	Quercus agrifolia	10"				x	Grading
9	Quercus agrifolia	20"				x	Grading
10	Quercus agrifolia	12"13"				x	Grading
11	Quercus agrifolia	13"10"7"				x	Grading
12	Quercus agrifolia	12"13"				x	Grading
13	Quercus agrifolia	20"13"				x	Grading Within Key
14	Quercus agrifolia	11"8"6"	x				
15 H. T	Quercus agrifolia	42"	x				
16	Quercus agrifolia	13"21"18"10"21"6"	x				
17	Quercus agrifolia	16"13"	x				
	SHEET 7 OF 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
18	Quercus agrifolia	20"	x				
19	Quercus agrifolia	15"	x				
20	Quercus agrifolia	17"	x				
21	Quercus agrifolia	22"	x				
22	Quercus agrifolia	13"	x				
23	Quercus agrifolia	7"6"6"	x				
24	Quercus agrifolia	10"7"6"	x				
25	Quercus agrifolia	12"	x				
26	Quercus agrifolia	19"15"10"	x				
27	Quercus agrifolia	10"8"			x		Grading
28	Quercus agrifolia	3"			x		Grading
29	Quercus agrifolia	5"3"			x		Grading
30	Quercus agrifolia	6"				x	Grading
31	Quercus agrifolia	11"12"8"				x	Grading
32	Quercus agrifolia	18"9"7"				x	Grading
33	Quercus agrifolia	19"				x	Grading
34	Quercus agrifolia	5"4"3"				x	Grading
35	Quercus agrifolia	9"	x				
36	Quercus agrifolia	13"14"13"15"	x				
37	Quercus agrifolia	6"6"4"	x				
38	Quercus agrifolia	4"	x				
39	Quercus agrifolia	14"11"12"12"13"10"13"	x				
40	Quercus agrifolia	13"	x				
41	Quercus agrifolia	9"	x				
42	Quercus agrifolia	11"8"	x				
43	Quercus agrifolia	20"19"14"	x				
44	Quercus agrifolia	25"14"	x				
45	Quercus agrifolia	20"8"	x				
46	Quercus berber.	3"4"4"4"3"3"	x				
47	Quercus agrifolia	9"	x				
48	Quercus agrifolia	19"22"14"	x				
49	Quercus agrifolia	22"19"	x				
50	Quercus agrifolia	6"	x				
51	Quercus agrifolia	23"20"	x				
52	Quercus agrifolia	16"15"10"	x				
53	Quercus agrifolia	15"13"6"	x				
54	Quercus agrifolia	20"	x				
55	Quercus agrifolia	7"4"	x				
56	Quercus agrifolia	42"11"	x				
57	Quercus agrifolia	6"6"4"3"3"	x				
351	Quercus berber.	2"2"2"2"2"2"3"3"				x	Grading
353	Quercus agrifolia	20"10"12"8"5"4"3"	x				
	SHEET 5 OF 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
58	Quercus agrifolia	4"				x	Grading
59	Quercus agrifolia	4"5				x	Grading
60	Quercus agrifolia	19"				x	Grading
61	Quercus agrifolia	15"16"				x	Grading
62	Quercus agrifolia	16"11"7"				x	Grading
63	Quercus agrifolia	17"				x	Grading
64	Quercus agrifolia	17"20"				x	Grading
65	Quercus agrifolia	11"				x	Grading
66	Quercus agrifolia	5"				x	Grading
67	Quercus agrifolia	17"15"				x	Grading
68	Quercus agrifolia	14"				x	Grading
69	Quercus agrifolia	10"				x	Grading
70	Quercus agrifolia	19"				x	Grading
71	Quercus agrifolia	22"				x	Grading
72	Quercus agrifolia	5"4"				x	Grading
73	Quercus agrifolia	12"				x	Grading
74	Quercus agrifolia	32"			x		Grading
75	Quercus agrifolia	9"			x		Grading
76	Quercus agrifolia	10"16"			x		Grading
77	Quercus agrifolia	18"17"7"			x		Grading
78	Quercus agrifolia	11"	x				
79	Quercus agrifolia	8"	x				
80	Quercus agrifolia	3"	x				
81	Quercus agrifolia	8"			x		Grading
82	Quercus agrifolia	13"			x		Grading
83	Quercus agrifolia	10"8"			x		Grading
84	Quercus agrifolia	4"4"3"2"			x		Grading
85	Quercus agrifolia	5"			x		Grading
86	Quercus agrifolia	8"			x		Grading
87	Quercus agrifolia	8"	x				
88	Quercus agrifolia	11"	x				
89	Quercus agrifolia	20"18"15"	x				
90	Quercus agrifolia	20"15"			x		Grading
91	Quercus agrifolia	16"18"12"			x		Grading
92	Quercus agrifolia	6"			x		Grading
93	Quercus agrifolia	8"11"				x	Grading
94	Quercus agrifolia	16"8"16"26"				x	Grading
95	Quercus agrifolia	7"				x	Grading
96	Quercus agrifolia	16"13"				x	Grading
97	Quercus agrifolia	14"				x	Grading
98	Quercus agrifolia	16"				x	DEAD
99	Quercus agrifolia	10"8"				x	Grading
100	Quercus agrifolia	25"				x	Grading
101	Quercus agrifolia	21"20"12"10'				x	Grading

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
102	Quercus agrifolia	15"			x		Sewer, SD, Deck
103	Quercus agrifolia	22"				x	Dead
104	Quercus agrifolia	14"16"	x				
105	Quercus berber.	6"	x				
106	Quercus agrifolia	9"		x			Deck
107	Quercus agrifolia	9"5"			x		New Walk
108	Quercus agrifolia	24"			x		New Walk
109	Quercus agrifolia	18"		x			Sewer, SD, Deck
110	Quercus agrifolia	23"			x		Sewer, SD, Deck
111	Quercus agrifolia	12"17"14"14"	x				Sewer, SD, Deck
112	Quercus agrifolia	22"		x			Sewer, SD
113	Quercus agrifolia	11"8"		x			Sewer, SD
114	Quercus agrifolia	14"	x				
115	Quercus agrifolia	12"	x				
116	Quercus agrifolia	15"	x				
117	Quercus agrifolia	12"18"	x				
118	Quercus agrifolia	9"	x				
119	Quercus agrifolia	10"	x				
120	Quercus berber.	8"7"9"			x		Sewer. SD, Future Walk
121	Quercus agrifolia	6"			x		Future Walk
122	Quercus agrifolia	13"			x		Future Walk
123	Quercus agrifolia	17"15"			x		Future Walk
124	Quercus agrifolia	13"12"	x				
125	Quercus agrifolia	20"			x		Future Walk
128	Quercus agrifolia	4"4"3"2"	x				
129	Quercus agrifolia	14"	x				
130	Quercus agrifolia	10"			x		Grading
131	Quercus berber.	7"			x		Grading
132	Quercus agrifolia	18"4"			x		Grading
133	Quercus agrifolia	16"			x		Grading
134	Quercus agrifolia	8"7"			x		Grading
	Sheet 6 of 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
126	Quercus agrifolia	9"	x				
127	Quercus berber.	9"8"7"	x				
135	Quercus berber.	5"2"		x			Grading
136	Quercus berber.	8"7"	x				
137	Quercus agrifolia	14"	x				
138	Quercus agrifolia	15"11"	x				
139	Quercus berber.	6"	x				
140	Quercus berber.	7"	x				
141	Quercus agrifolia	6"	x				
142	Quercus agrifolia	17"	x				
143	Quercus agrifolia	13"		x			Grading
144	Quercus agrifolia	7"		x			Grading
145	Quercus berber.	5"5"		x			Grading
146	Quercus berber.	5"2"2"	x				
147	Quercus berber.	7"6"	x				
148	Quercus berber.	8"	x				
149	Quercus agrifolia	10"	x				
150	Quercus agrifolia	10"	x				
151	Quercus agrifolia	12"		x			Retaining Wall
152	Quercus agrifolia	15"				x	Grading
153	Quercus agrifolia	15"				x	Grading
154	Quercus berber.	11"			x		Grading
155	Quercus berber.	5"		x			Retaining Wall
156	Quercus agrifolia	5"3"	x				
157	Quercus agrifolia	11"	x				
158	Quercus berber.	7"	x				
159	Quercus berber.	4"4"3"2"		x			Future Parking Lot
160	Quercus agrifolia	6"4"	x				
161	Quercus agrifolia	6"	x				
162	Quercus berber.	6"	x				
163	Quercus agrifolia	23"	x				
164	Quercus agrifolia	14"	x				
165	Quercus berber.	14"	x				
166	Quercus berber.	7"7"	x				
167	Quercus agrifolia	14"	x				
168	Quercus berber.	8"7"	x				
169	Quercus agrifolia	20"			x		Future Driveway
170	Quercus agrifolia	10"12"12"16"				x	Fell during storm
171	Quercus agrifolia	10"				x	Fell during storm
172	Quercus agrifolia	9"	x				
173	Quercus agrifolia	23"	x				
174	Quercus agrifolia	17"	x				
175	Quercus agrifolia	22"	x				
176	Quercus agrifolia	21"		x		x	Grading

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
177	Quercus agrifolia	14"13"				x	Grading
178	Quercus agrifolia	20"				x	Grading
179	Quercus agrifolia	15"15"				x	Grading
180	Quercus agrifolia	12:11"6"				x	Grading
181	Quercus agrifolia	5"		x			Grading
182	Quercus agrifolia	19"3"	x				
183	Quercus agrifolia	6"	x				
184	Quercus agrifolia	14"8"	x				
185	Quercus agrifolia	6"			x		Grading
186	Quercus agrifolia	14"13"			x		Grading
187	Quercus agrifolia	18"				x	Grading
188	Quercus agrifolia	12"				x	Grading
189	Quercus agrifolia	27"				x	Grading
190	Quercus agrifolia	14"13"13"	x				
191	Quercus agrifolia	24"14"		x			Grading
192	Quercus agrifolia	19"	x				
193	Quercus agrifolia	15"9"11"10"12"			x		Future Parking Lot
194	Quercus agrifolia	13"	x				
195	Quercus agrifolia	18"			x		Future Parking Lot
196	Quercus agrifolia	12"			x		Future Parking Lot
197	Quercus agrifolia	14"			x		Future Parking Lot
198	Quercus agrifolia.	21"			x		Future Parking Lot
199	Quercus agrifolia.	14"10"	x				
200	Quercus agrifolia	7"	x				
201	Quercus agrifolia	12"8"	x				
202	Quercus agrifolia	7"6"5"	x				
203	Quercus agrifolia	4"	x				
204	Quercus agrifolia	4"5"	x				
205	Quercus agrifolia	5"3"	x				
206	Quercus agrifolia	3"3"3"	x				
207	Quercus agrifolia	6"5"4"	x				
208	Quercus agrifolia	3"	x				
209	Quercus agrifolia	3"	x				
210	Quercus agrifolia	4"4"3"2"2"	x				
211	Quercus agrifolia	3"4"3"3"2"	x				
212	Quercus agrifolia	3"	x				
213	Quercus agrifolia	3"	x				
214	Quercus agrifolia	3"4"2"	x				
215	Quercus agrifolia	8"	x				
216	Quercus agrifolia	25"	x				
217	Quercus agrifolia	33"	x				
218	Quercus agrifolia	5"3"4"	x				
219	Quercus agrifolia	28"	x				
220	Quercus agrifolia	14"9"8"	x				

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
221	Quercus agrifolia	14"13"	x				
222 H.T	Quercus agrifolia	40"			x		Grading
223	Quercus agrifolia	18"15"			x		Grading
224	Quercus agrifolia	24"			x		Grading
225	Quercus agrifolia	28"	x				
226 H.T	Quercus agrifolia	48"	x				
227	Quercus agrifolia	22"	x				
228	Quercus agrifolia	20"	x				
229	Quercus agrifolia	22"	x				
230	Quercus agrifolia	19"	x				
231	Quercus agrifolia	14"	x				
232	Quercus agrifolia	27"		x			Grading
233	Quercus agrifolia	11"				x	Dead
234	Quercus agrifolia	30"16"			x		Grading
235 H.T	Quercus agrifolia	35"		x			Grading
236	Quercus agrifolia	28"		x			Grading
237	Quercus agrifolia	20"				x	Grading
238	Quercus agrifolia	29"27"			x		Grading
239	Quercus agrifolia	32"				x	Access Road
240 H.T	Quercus agrifolia	48"			x		Access Road
241	Quercus agrifolia	16"	x				
242	Quercus agrifolia.	14"	x				
243	Quercus agrifolia.	14"	x				
244 H.T	Quercus agrifolia	29"26"	x				
245 H.T	Quercus agrifolia	39"	x				
246 H.T	Quercus agrifolia	34"	x				
247	Quercus agrifolia	18"	x				
248	Quercus agrifolia	25"	x				
249	Quercus agrifolia	18"	x				
250	Quercus agrifolia	15"	x				
251	Quercus agrifolia	19"9"	x				
252	Quercus agrifolia	10"8"8"7"	x				
253	Quercus agrifolia	19"	x				
254	Quercus agrifolia	7"	x				
255 H.T	Quercus agrifolia	45"	x				
256	Quercus agrifolia	9"	x				
257	Quercus agrifolia	30"	x				
258 H.T	Quercus agrifolia	54"	x				
259 H.T	Quercus agrifolia	66"	x				
260 H.T	Quercus agrifolia	38"	x				
261	Quercus agrifolia	32"	x				
262 H.T	Quercus agrifolia	32"22"	x				
263	Quercus agrifolia	21"	x				
264	Quercus agrifolia	21"21"17"19"	x				

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
265	Quercus agrifolia	22"	x				
266 H.T	Quercus agrifolia	34"			x		Future Walk, SD. Sewer
267	Quercus agrifolia	24"21"21"	x				
268	Quercus agrifolia	30"20"19"			x		Future Walk, SD.Sewer
269	Quercus agrifolia	17"	x				
270 H.T	Quercus agrifolia	42"	x				
271	Quercus agrifolia	17"15"	x				
272	Quercus agrifolia	20"	x				
273	Quercus agrifolia	24"			x		Futrure Walk
274 H.T	Quercus agrifolia	35"27"			x		Future Walk
275	Quercus agrifolia	22"			x		Future Walk
276	Quercus agrifolia	14"	x				
277	Quercus agrifolia	25"	x				
	SHEET 3 OF 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
278	Quercus agrifolia	30"20	x				
279	Quercus agrifolia	3"		x			Future Parking Lot
280 H.T	Quercus agrifolia	35"30"	x				
281	Quercus agrifolia	29"15"	x				
282 H. T	Quercus agrifolia	32"34"	x				
283	Quercus agrifolia	19"18"	x				
284	Quercus agrifolia	22"19"18"13"	x				
285	Quercus agrifolia	8"6"5"6"		x			Future Parking Lot
286	Quercus agrifolia	3"2"2"			x		Future Parking Lot
287	Quercus agrifolia	19"18"			x		Future Parking Lot
288 H. T	Quercus agrifolia	38"	x				
289 H. T	Quercus agrifolia	36"34"	x				
290	Quercus agrifolia	20"	x				
291	Quercus agrifolia	21"20"19"14"	x				
292 H. T	Quercus agrifolia	38"	x				
293	Quercus agrifolia	10"	x				
294	Quercus agrifolia	7"	x				
295	Quercus agrifolia	9"8"	x				
296	Quercus agrifolia	18"	x				
297	Quercus agrifolia	9"9"7"6"8"	x				
298	Quercus agrifolia	7"6"6"6"6"	x				
299	Quercus agrifolia.	4"	x				
300	Quercus agrifolia.	7"6"	x				
301	Quercus agrifolia	16"16"	x				
302	Quercus agrifolia	18"	x				
303	Quercus agrifolia	28"	x				
304	Quercus agrifolia	12"	x				
305	Quercus agrifolia	4"	x				
306	Quercus agrifolia	17"	x				
307	Quercus agrifolia	7"	x				
308	Quercus agrifolia	8"7"	x				
309	Quercus agrifolia	14"			x		Pedestrian Walk
310	Quercus agrifolia	8"			x		Pedestrian Walk
311	Quercus agrifolia	10"			x		Pedestrian Walk
312	Quercus agrifolia	9"			x		Pedestrian Walk
313	Quercus agrifolia	18"		x			Pedestrian Walk
314	Quercus agrifolia	5"4"		x			Pedestrian Walk
315	Quercus agrifolia	5"		x			Pedestrian Walk
316	Quercus agrifolia	10"			x		Pedestrian Walk
317	Quercus agrifolia	8"		x			Pedestrian Walk
318	Quercus agrifolia	7"6"	x				
319	Quercus agrifolia	7"3"	x				
320	Quercus agrifolia	8"	x				
	Sheet 6 of 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
321	Quercus agrifolia	8"7"		x			Pedestrian Walk
322	Quercus agrifolia	5"		x			Pedestrian Walk
323 H. T	Quercus agrifolia	32"32"19"			x		Pedestrian Walk
324 H. T	Quercus agrifolia	38"	x				
325	Quercus agrifolia	20"			x		Future Walk
	Sheet 6 0f 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
326	Quercus agrifolia	33"	x				
327 H.T	Quercus agrifolia	63"	x				
328	Quercus agrifolia	18"15"	x				
329 H.T	Quercus agrifolia	30"29"	x				
330 H.T	Quercus agrifolia	26"24"23"	x				
331 H.T	Quercus agrifolia	37"	x				
332 H.T	Quercus agrifolia	34"	x				
333 H.T	Quercus agrifolia	35"	x				
334	Quercus agrifolia	36"20"17"20"	x				
335 H.T	Quercus agrifolia	32"28"	x				
336	Quercus agrifolia	24"19"	x				
337 H.T	Quercus agrifolia	70"	x				
338	Quercus agrifolia	30"	x				
339	Quercus agrifolia	23"	x				
340	Quercus agrifolia	19"12"11"8"17"	x				
341 H.T	Quercus agrifolia	39"	x				
342	Quercus agrifolia	25"	x				
343 H.T	Quercus agrifolia	25"29"18"	x				
344	Quercus agrifolia	22"17"14"	x				
345	Quercus agrifolia	18"15"14"8"	x				
346	Quercus agrifolia	24"19"15"	x				
347	Quercus agrifolia	20"19"	x				
348	Quercus agrifolia	22"20"24"	x				
349 H.T	Quercus agrifolia	58"	x				
350	Quercus agrifolia	32"	x				
	SHEET 2 OF 7						

SUMMARY OF DATA

TREE #	SPECIES	DIAMETER @ 4.5 FT DBH	NO IMPACT	WK WITHIN 5 Ft. ZONE	WK WITHIN DRIPLINE	RE-MOVE	DESCRIPTION OF IMPACT
352	Quercus agrifolia	6"4"3"3"2"				x	Grading
	SHEET 4 OF 7						

SECTION 2

METHOD USED FOR THE TREE APPRAISAL

The GUIDE FOR PLANT APPRAISAL 9th EDITION Authored by Representatives to the Council of Tree & Landscape Appraisers was used in preparing the Tree Appraisals.

The TRUNK FORMULA METRHOD was the procedure used for the Tree Appraisal.

The 9th Edition was: Edited, published and copyrighted by the INTERNATIONAL SOCIETY of ARBORICULTURE

NINTH EDITION 2000

TREE APPRAISAL

TREE NUMBER	6
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			16	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		200.96	201			
APPRAISED TREE TRUNK INCREASE			177			
BASIC TREE COST			$14,024.40			
APPRAISED VALUE			**$6,479.27**			

TREE NUMBER	7
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			9	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		63.59	64			
APPRAISED TREE TRUNK INCREASE			40			
BASIC TREE COST			$5,475.60			
APPRAISED VALUE			**$2,529.73**			

TREE APPRAISAL

TREE NUMBER	8
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			10	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		78.50	79			
APPRAISED TREE TRUNK INCREASE			55			
BASIC TREE COST			$6,411.60			
APPRAISED VALUE			**$2,962.16**			

TREE NUMBER	9
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			20	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		314.00	314			
APPRAISED TREE TRUNK INCREASE			290			
BASIC TREE COST			$21,075.60			
APPRAISED VALUE			**$9,736.93**			

TREE APPRAISAL

TREE NUMBER	10
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			16	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		200.96	201			
APPRAISED TREE TRUNK INCREASE			177			
BASIC TREE COST			$14,024.40			
APPRAISED VALUE			**$6,479.27**			

TREE NUMBER	11
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			30	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		706.50	707			
APPRAISED TREE TRUNK INCREASE			683			
BASIC TREE COST			$45,598.80			
APPRAISED VALUE			**$21,066.65**			

TREE APPRAISAL

TREE NUMBER	12
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION		70%				
TRUNK DIAMETER		25	SITE	CONT.	PLACE	
LOCATION			80%	70%	70%	73%
SPECIES RATING		90%				
REPLACEMENT TREE SIZE		5.50	23.75			
REPLACEMENT TREE COST		$1,482.00				
INSTALLATION COST		$1,482.00				
INSTALLED TREE COST		$2,964.00				
UNIT TREE COST		$62.40				
APPRAISED TRUNK AREA	490.63	491				
APPRAISED TREE TRUNK INCREASE		467				
BASIC TREE COST		$32,120.40				
APPRAISED VALUE		**$14,839.62**				

TREE NUMBER	13
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION		70%				
TRUNK DIAMETER		23	SITE	CONT.	PLACE	
LOCATION			80%	70%	70%	73%
SPECIES RATING		90%				
REPLACEMENT TREE SIZE		5.50	23.75			
REPLACEMENT TREE COST		$1,482.00				
INSTALLATION COST		$1,482.00				
INSTALLED TREE COST		$2,964.00				
UNIT TREE COST		$62.40				
APPRAISED TRUNK AREA	415.27	415				
APPRAISED TREE TRUNK INCREASE		391				
BASIC TREE COST		$27,378.00				
APPRAISED VALUE		**$12,648.64**				

TREE APPRAISAL

TREE NUMBER	30
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			6	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		28.26	28			
APPRAISED TREE TRUNK INCREASE			4			
BASIC TREE COST			$3,229.20			
APPRAISED VALUE			**$1,491.89**			

TREE NUMBER	31
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			31	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		754.39	739	ATA		
APPRAISED TREE TRUNK INCREASE			715			
BASIC TREE COST			$47,595.60			
APPRAISED VALUE			**$21,989.17**			

TREE APPRAISAL

TREE NUMBER	32
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			34	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		907.46	882			
APPRAISED TREE TRUNK INCREASE			858			
BASIC TREE COST			$56,518.80			
APPRAISED VALUE			**$26,111.69**			

TREE NUMBER	33
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			80%			
TRUNK DIAMETER			19	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		283.39	283			
APPRAISED TREE TRUNK INCREASE			259			
BASIC TREE COST			$19,141.20			
APPRAISED VALUE			**$10,106.55**			

TREE APPRAISAL

TREE NUMBER	34
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			12	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		113.04	113			
APPRAISED TREE TRUNK INCREASE			89			
BASIC TREE COST			$8,533.20			
APPRAISED VALUE			**$3,942.34**			

TREE NUMBER	351
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Scrub Oak (*Quercus berberidfolia*)					
CONDITION			70%			
TRUNK DIAMETER			18	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		254.34	254			
APPRAISED TREE TRUNK INCREASE			230			
BASIC TREE COST			$17,331.60			
APPRAISED VALUE			**$8,007.20**			

TREE APPRAISAL

TREE NUMBER	58
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			4	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		12.56	13			
APPRAISED TREE TRUNK INCREASE			-11			
BASIC TREE COST			$2,293.20			
APPRAISED VALUE			**$1,059.46**			

TREE NUMBER	59
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			60%			
TRUNK DIAMETER			9	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		63.59	64			
APPRAISED TREE TRUNK INCREASE			40			
BASIC TREE COST			$5,475.60			
APPRAISED VALUE			**$2,168.34**			

TREE APPRAISAL

TREE NUMBER	60
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			19	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		283.39	283			
APPRAISED TREE TRUNK INCREASE			259			
BASIC TREE COST			$19,141.20			
APPRAISED VALUE			**$8,843.23**			

TREE NUMBER	61
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			31	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		754.39	739	ATA		
APPRAISED TREE TRUNK INCREASE			715			
BASIC TREE COST			$47,595.60			
APPRAISED VALUE			**$21,989.17**			

TREE APPRAISAL

TREE NUMBER	62
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			34	SITE	CONT.	PLACE
LOCATION				80%	70%	70%	73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		907.46	882	ATA		
APPRAISED TREE TRUNK INCREASE			858			
BASIC TREE COST			$56,518.80			
APPRAISED VALUE			**$26,111.69**			

TREE NUMBER	63
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			17	SITE	CONT.	PLACE
LOCATION				80%	70%	70%	73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		226.87	227			
APPRAISED TREE TRUNK INCREASE			203			
BASIC TREE COST			$15,646.80			
APPRAISED VALUE			**$7,228.82**			

TREE APPRAISAL

TREE NUMBER	64
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			37	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		1074.67	1018	ATA		
APPRAISED TREE TRUNK INCREASE			994			
BASIC TREE COST			$65,005.20			
APPRAISED VALUE			**$30,032.40**			

TREE NUMBER	65
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			11	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		94.99	95			
APPRAISED TREE TRUNK INCREASE			71			
BASIC TREE COST			$7,410.00			
APPRAISED VALUE			**$3,423.42**			

TREE APPRAISAL

TREE NUMBER	66
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION		70%				
TRUNK DIAMETER		5	SITE	CONT.	PLACE	
LOCATION			80%	70%	70%	73%
SPECIES RATING		90%				
REPLACEMENT TREE SIZE		5.50	23.75			
REPLACEMENT TREE COST		$1,482.00				
INSTALLATION COST		$1,482.00				
INSTALLED TREE COST		$2,964.00				
UNIT TREE COST		$62.40				
APPRAISED TRUNK AREA	19.63	20				
APPRAISED TREE TRUNK INCREASE		-4				
BASIC TREE COST		$2,730.00				
APPRAISED VALUE		**$1,261.26**				

TREE NUMBER	67
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION		70%				
TRUNK DIAMETER		29	SITE	CONT.	PLACE	
LOCATION			80%	70%	70%	73%
SPECIES RATING		90%				
REPLACEMENT TREE SIZE		5.50	23.75			
REPLACEMENT TREE COST		$1,482.00				
INSTALLATION COST		$1,482.00				
INSTALLED TREE COST		$2,964.00				
UNIT TREE COST		$62.40				
APPRAISED TRUNK AREA	660.19	660				
APPRAISED TREE TRUNK INCREASE		636				
BASIC TREE COST		$42,666.00				
APPRAISED VALUE		**$19,711.69**				

TREE APPRAISAL

TREE NUMBER	68
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			14	SITE	CONT.	PLACE
LOCATION				80%	70%	70%	73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		153.86	154			
APPRAISED TREE TRUNK INCREASE			130			
BASIC TREE COST			$11,091.60			
APPRAISED VALUE			**$5,124.32**			

TREE NUMBER	69
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			60%			
TRUNK DIAMETER			10	SITE	CONT.	PLACE
LOCATION				80%	70%	70%	73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		78.50	79			
APPRAISED TREE TRUNK INCREASE			55			
BASIC TREE COST			$6,411.60			
APPRAISED VALUE			**$2,538.99**			

TREE APPRAISAL

TREE NUMBER	70
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			19	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		283.39	283			
APPRAISED TREE TRUNK INCREASE			259			
BASIC TREE COST			$19,141.20			
APPRAISED VALUE			**$8,843.23**			

TREE NUMBER	71
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			22	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		379.94	380			
APPRAISED TREE TRUNK INCREASE			356			
BASIC TREE COST			$25,194.00			
APPRAISED VALUE			**$11,639.63**			

TREE APPRAISAL

TREE NUMBER	72
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			9	SITE	CONT.	PLACE
LOCATION				80%	70%	70%	73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		63.59	64			
APPRAISED TREE TRUNK INCREASE			40			
BASIC TREE COST			$5,475.60			
APPRAISED VALUE			**$2,529.73**			

TREE NUMBER	73
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			12	SITE	CONT.	PLACE
LOCATION				80%	70%	70%	73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		113.04	113			
APPRAISED TREE TRUNK INCREASE			89			
BASIC TREE COST			$8,533.20			
APPRAISED VALUE			**$3,942.34**			

TREE APPRAISAL

TREE NUMBER	93
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION		70%				
TRUNK DIAMETER		19	SITE	CONT.	PLACE	
LOCATION			80%	70%	70%	73%
SPECIES RATING		90%				
REPLACEMENT TREE SIZE		5.50	23.75			
REPLACEMENT TREE COST		$1,482.00				
INSTALLATION COST		$1,482.00				
INSTALLED TREE COST		$2,964.00				
UNIT TREE COST		$62.40				
APPRAISED TRUNK AREA	283.39	283				
APPRAISED TREE TRUNK INCREASE		259				
BASIC TREE COST		$19,141.20				
APPRAISED VALUE		**$8,843.23**				

TREE NUMBER	94
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION		70%				
TRUNK DIAMETER		66	SITE	CONT.	PLACE	
LOCATION			80%	70%	70%	73%
SPECIES RATING		90%				
REPLACEMENT TREE SIZE		5.50	23.75			
REPLACEMENT TREE COST		$1,482.00				
INSTALLATION COST		$1,482.00				
INSTALLED TREE COST		$2,964.00				
UNIT TREE COST		$62.40				
APPRAISED TRUNK AREA	3419.46	2028	ATA			
APPRAISED TREE TRUNK INCREASE		2004				
BASIC TREE COST		$128,029.20				
APPRAISED VALUE		**$59,149.49**				

TREE APPRAISAL

TREE NUMBER	95
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION		70%				
TRUNK DIAMETER		7	SITE	CONT.	PLACE	
LOCATION			80%	70%	70%	73%
SPECIES RATING		90%				
REPLACEMENT TREE SIZE		5.50	23.75			
REPLACEMENT TREE COST		$1,482.00				
INSTALLATION COST		$1,482.00				
INSTALLED TREE COST		$2,964.00				
UNIT TREE COST		$62.40				
APPRAISED TRUNK AREA	38.47	38				
APPRAISED TREE TRUNK INCREASE		14				
BASIC TREE COST		$3,853.20				
APPRAISED VALUE		**$1,780.18**				

TREE NUMBER	96
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION		70%				
TRUNK DIAMETER		29	SITE	CONT.	PLACE	
LOCATION			80%	70%	70%	73%
SPECIES RATING		90%				
REPLACEMENT TREE SIZE		5.50	23.75			
REPLACEMENT TREE COST		$1,482.00				
INSTALLATION COST		$1,482.00				
INSTALLED TREE COST		$2,964.00				
UNIT TREE COST		$62.40				
APPRAISED TRUNK AREA	660.19	660				
APPRAISED TREE TRUNK INCREASE		636				
BASIC TREE COST		$42,666.00				
APPRAISED VALUE		**$19,711.69**				

TREE APPRAISAL

TREE NUMBER	97
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			14	SITE	CONT.	PLACE
LOCATION				80%	70%	70%	73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		153.86	154			
APPRAISED TREE TRUNK INCREASE			130			
BASIC TREE COST			$11,091.60			
APPRAISED VALUE			**$5,124.32**			

TREE NUMBER	98
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			16	SITE	CONT.	PLACE
LOCATION				80%	70%	70%	73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		200.96	201			
APPRAISED TREE TRUNK INCREASE			177			
BASIC TREE COST			$14,024.40			
APPRAISED VALUE			**$6,479.27**			

TREE APPRAISAL

TREE NUMBER	99
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			18	SITE	CONT.	PLACE
LOCATION				80%	70%	70%	73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		254.34	254			
APPRAISED TREE TRUNK INCREASE			230			
BASIC TREE COST			$17,331.60			
APPRAISED VALUE			**$8,007.20**			

TREE NUMBER	100
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			60%			
TRUNK DIAMETER			25	SITE	CONT.	PLACE
LOCATION				80%	70%	70%	73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		490.63	491			
APPRAISED TREE TRUNK INCREASE			467			
BASIC TREE COST			$32,120.40			
APPRAISED VALUE			**$12,719.68**			

TREE APPRAISAL

TREE NUMBER	101
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			66	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		3419.46	2028	ATA		
APPRAISED TREE TRUNK INCREASE			2004			
BASIC TREE COST			$128,029.20			
APPRAISED VALUE			**$59,149.49**			

TREE NUMBER	152
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			15	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		176.63	177			
APPRAISED TREE TRUNK INCREASE			153			
BASIC TREE COST			$12,526.80			
APPRAISED VALUE			**$5,787.38**			

TREE APPRAISAL

TREE NUMBER	153
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			15	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		176.63	177			
APPRAISED TREE TRUNK INCREASE			153			
BASIC TREE COST			$12,526.80			
APPRAISED VALUE			**$5,787.38**			

TREE NUMBER	176
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			21	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		346.19	346			
APPRAISED TREE TRUNK INCREASE			322			
BASIC TREE COST			$23,072.40			
APPRAISED VALUE			**$10,659.45**			

TREE APPRAISAL

TREE NUMBER	177
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION		60%				
TRUNK DIAMETER		27	SITE	CONT.	PLACE	
LOCATION			80%	70%	70%	73%
SPECIES RATING		90%				
REPLACEMENT TREE SIZE		5.50	23.75			
REPLACEMENT TREE COST		$1,482.00				
INSTALLATION COST		$1,482.00				
INSTALLED TREE COST		$2,964.00				
UNIT TREE COST		$62.40				
APPRAISED TRUNK AREA	572.27	572				
APPRAISED TREE TRUNK INCREASE		548				
BASIC TREE COST		$37,174.80				
APPRAISED VALUE		**$14,721.22**				

TREE NUMBER	178
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION		60%				
TRUNK DIAMETER		20	SITE	CONT.	PLACE	
LOCATION			80%	70%	70%	73%
SPECIES RATING		90%				
REPLACEMENT TREE SIZE		5.50	23.75			
REPLACEMENT TREE COST		$1,482.00				
INSTALLATION COST		$1,482.00				
INSTALLED TREE COST		$2,964.00				
UNIT TREE COST		$62.40				
APPRAISED TRUNK AREA	314.00	314				
APPRAISED TREE TRUNK INCREASE		290				
BASIC TREE COST		$21,075.60				
APPRAISED VALUE		**$8,345.94**				

TREE APPRAISAL

TREE NUMBER	179
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			60%			
TRUNK DIAMETER			30	SITE	CONT.	PLACE	
LOCATION				80%	70%	70%	73%
SPECIES RATING			90%				
REPLACEMENT TREE SIZE			5.50	23.75			
REPLACEMENT TREE COST			$1,482.00				
INSTALLATION COST			$1,482.00				
INSTALLED TREE COST			$2,964.00				
UNIT TREE COST			$62.40				
APPRAISED TRUNK AREA		706.50	707				
APPRAISED TREE TRUNK INCREASE			683				
BASIC TREE COST			$45,598.80				
APPRAISED VALUE			**$18,057.12**				

TREE NUMBER	180
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			60%			
TRUNK DIAMETER			29	SITE	CONT.	PLACE	
LOCATION				80%	70%	70%	73%
SPECIES RATING			90%				
REPLACEMENT TREE SIZE			5.50	23.75			
REPLACEMENT TREE COST			$1,482.00				
INSTALLATION COST			$1,482.00				
INSTALLED TREE COST			$2,964.00				
UNIT TREE COST			$62.40				
APPRAISED TRUNK AREA		660.19	660				
APPRAISED TREE TRUNK INCREASE			636				
BASIC TREE COST			$42,666.00				
APPRAISED VALUE			**$16,895.74**				

TREE APPRAISAL

TREE NUMBER	187
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			60%			
TRUNK DIAMETER			18	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		254.34	254			
APPRAISED TREE TRUNK INCREASE			230			
BASIC TREE COST			$17,331.60			
APPRAISED VALUE			**$6,863.31**			

TREE NUMBER	188
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			60%			
TRUNK DIAMETER			12	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		113.04	113			
APPRAISED TREE TRUNK INCREASE			89			
BASIC TREE COST			$8,533.20			
APPRAISED VALUE			**$3,379.15**			

TREE APPRAISAL

TREE NUMBER	189
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			60%			
TRUNK DIAMETER			24	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		452.16	452			
APPRAISED TREE TRUNK INCREASE			428			
BASIC TREE COST			$29,686.80			
APPRAISED VALUE			**$11,755.97**			

TREE NUMBER	239
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Coast Live Oak (*Quercus agrifolia*)					
CONDITION			70%			
TRUNK DIAMETER			32	SITE	CONT.	PLACE
LOCATION				80%	70%	70% 73%
SPECIES RATING			90%			
REPLACEMENT TREE SIZE			5.50	23.75		
REPLACEMENT TREE COST			$1,482.00			
INSTALLATION COST			$1,482.00			
INSTALLED TREE COST			$2,964.00			
UNIT TREE COST			$62.40			
APPRAISED TRUNK AREA		803.84	804	ATA		
APPRAISED TREE TRUNK INCREASE			780			
BASIC TREE COST			$51,651.60			
APPRAISED VALUE			**$23,863.04**			


TREE APPRAISAL

TREE NUMBER	352
PROPERTY	Master's College
APPRAISER (ARBORIST)	Robert Hansen
DATE	September 31, 2005

SPECIES	Scrub Oak (Quercus berberidfolia)					
CONDITION		70%				
TRUNK DIAMETER		18	SITE	CONT.	PLACE	
LOCATION			80%	70%	70%	73%
SPECIES RATING		90%				
REPLACEMENT TREE SIZE		5.50	23.75			
REPLACEMENT TREE COST		$1,482.00				
INSTALLATION COST		$1,482.00				
INSTALLED TREE COST		$2,964.00				
UNIT TREE COST		$62.40				
APPRAISED TRUNK AREA	254.34	254				
APPRAISED TREE TRUNK INCREASE		230				
BASIC TREE COST		$17,331.60				
APPRAISED VALUE		**$8,007.20**				


SECTION 3

PICTURE PAGE







PICTURE PAGE




PICTURE PAGE






PICTURE PAGE







PICTURE PAGE




PICTURE PAGE




PICTURE PAGE





PICTURE PAGE




PICTURE PAGE



PICTURE PAGE



PICTURE PAGE





PICTURE PAGE






PICTURE PAGE



PICTURE PAGE




PICTURE PAGE




PICTURE PAGE





PICTURE PAGE







PICTURE PAGE





PICTURE PAGE






PICTURE PAGE




PICTURE PAGE



PICTURE PAGE




PICTURE PAGE



PICTURE PAGE



PICTURE PAGE




PICTURE PAGE



PICTURE PAGE



PICTURE PAGE





PICTURE PAGE





PICTURE PAGE






PICTURE PAGE




PICTURE PAGE



PICTURE PAGE




PICTURE PAGE




PICTURE PAGE



PICTURE PAGE




PICTURE PAGE



PICTURE PAGE



PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE



PICTURE PAGE



PICTURE PAGE



PICTURE PAGE



PICTURE PAGE





PICTURE PAGE



PICTURE PAGE






PICTURE PAGE



PICTURE PAGE



PICTURE PAGE






PICTURE PAGE




PICTURE PAGE



PICTURE PAGE






PICTURE PAGE



PICTURE PAGE



PICTURE PAGE



PICTURE PAGE



PICTURE PAGE



PICTURE PAGE



PICTURE PAGE



PICTURE PAGE



PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE



PICTURE PAGE



PICTURE PAGE



PICTURE PAGE



PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE



PICTURE PAGE




PICTURE PAGE






PICTURE PAGE



PICTURE PAGE





PICTURE PAGE






PICTURE PAGE



PICTURE PAGE





PICTURE PAGE



PICTURE PAGE




PICTURE PAGE



PICTURE PAGE



PICTURE PAGE



PICTURE PAGE



PICTURE PAGE




PICTURE PAGE




PICTURE PAGE



PICTURE PAGE





PICTURE PAGE



PICTURE PAGE



PICTURE PAGE




PICTURE PAGE



PICTURE PAGE




PICTURE PAGE




PICTURE PAGE







PICTURE PAGE




PICTURE PAGE





PICTURE PAGE





PICTURE PAGE




PICTURE PAGE



PICTURE PAGE



PICTURE PAGE




PICTURE PAGE




PICTURE PAGE



PICTURE PAGE







PICTURE PAGE




PICTURE PAGE




PICTURE PAGE



PICTURE PAGE



PICTURE PAGE




PICTURE PAGE



PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE



PICTURE PAGE



PICTURE PAGE



PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE



PICTURE PAGE





PICTURE PAGE



PICTURE PAGE






PICTURE PAGE



PICTURE PAGE





PICTURE PAGE




PICTURE PAGE



PICTURE PAGE




PICTURE PAGE





PICTURE PAGE





PICTURE PAGE



PICTURE PAGE



PICTURE PAGE



PICTURE PAGE




PICTURE PAGE



PICTURE PAGE




PICTURE PAGE




PICTURE PAGE



PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE



PICTURE PAGE




PICTURE PAGE



PICTURE PAGE




PICTURE PAGE





PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE




PICTURE PAGE



PICTURE PAGE




PICTURE PAGE



PICTURE PAGE





PICTURE PAGE

